Historic, archived document

Do not assume content reflects current scientific knowledge, policies, or practices.

UNITED STATES DEPARTMENT OF AGRICULTURE

DEPARTMENT BULLETIN No. 576

Washington, D. C.

Issued September 27, 1917
Revised June, 1925

THE MANUFACTURE OF COTTAGE CHEESE IN CREAMERIES AND MILK PLANTS

By ARNOLD O. DAHLBERG,¹ *Dairy Division, Bureau of Animal Industry*

Revised by K. J. MATHESON, *Bureau of Dairying*

CONTENTS

	Page.		Page.
Good raw material essential-----	1	Method of manufacture—Continued.	
Pasteurization of skim milk important	2	Draining and washing the curd-----	5
Equipment required-----	2	Salting and creaming-----	6
Pasteurizer-----	2	Packing and marketing-----	7
Cheese vat-----	2	Yield of cheese-----	8
Curd knives-----	3	Buttermilk as material for cheese-----	8
Curd pail-----	3	Making buttermilk cheese-----	9
Vat whey strainer-----	3	Cost of manufacture-----	9
Method of manufacture-----	3	Markets and prices-----	11
Ripening the milk-----	3	Summary-----	11
Cutting and heating the curd-----	3		

Cottage cheese, properly made, offers a most palatable and nutritious article of food at a price relatively low compared with the cost and nutritive value of many other foods, and the demand for it is increasing with the greater knowledge of its true value as a food. This variety of cheese is made from skim milk. The simplicity of the method of manufacture recommends its adoption by creameries and milk plants having skim milk which it is desired to dispose of to good advantage. Very little additional equipment is required, and the cost of manufacture is low, which enables the creamery to pay the patrons a good price for the skim milk.

GOOD RAW MATERIAL ESSENTIAL

As the quality of cottage cheese is entirely dependent upon flavor and texture, it is very important to have milk of a good clean flavor, free from any foreign odors. The maker can control the texture of cheese by the process of making; but if the flavor is to be controlled, good raw material is necessary.

¹ Mr. Dahlberg resigned Jan. 15, 1920.

PASTEURIZATION OF SKIM MILK IMPORTANT

It is advisable to pasteurize the fresh skim milk just as it comes from the separator, and to begin manufacturing as soon as possible, in order to control the fermentation or souring to the best advantage. No trouble need be experienced in making a high quality of cottage cheese, possessing both the characteristic flavor and body, from properly pasteurized skim milk of good quality. Pasteurizing the milk at a temperature of 145° F. for 30 minutes in no way affects the coagulability of the milk or the handling of the curd in making cottage cheese. A higher temperature, however, should be avoided, as it gives a fine curd which is much harder to handle during the process of manufacture. Perhaps the greater portion of the cottage cheese used is made from raw skim milk, but the benefits to be derived from proper pasteurization are so great as to make it highly advisable. Pasteurization adds but little to the cost of making and has the following important points in its favor.

1. It insures a food product free from all danger of disease-producing bacteria.

2. It makes it possible to exercise a more perfect control of souring through the use of pure-culture starters, thus insuring the formation of an acid curd giving the characteristic, mild, sour-milk flavor so much desired.

Pasteurization requires little additional work, if suitable equipment is available. The use of a pasteurizing vat, so elevated as to allow the pasteurized milk to run into the making vat by gravity, gives most satisfactory results.

EQUIPMENT REQUIRED

Any equipment needed for making cottage cheese, in addition to that already in the creamery or milk plant, depends upon the apparatus on hand and whether the skim milk is to be pasteurized. When a pasteurizer and a channel-bottomed vat are available, very little expense is necessary. Assuming that the skim milk is to be pasteurized, the following-named apparatus will be needed: Pasteurizer, channel-bottomed cheese vat, curd knives, curd pail, vat whey strainer.

PASTEURIZER

The holding system of pasteurization is to be preferred. It requires a pasteurizing vat which may also be used for cooling the skim milk to the ripening temperature, after which the milk is run into the making vat. The skim milk for more than one batch of cheese may be handled in one pasteurizing vat, provided all of it does not have to be taken care of at once.

In case the flash method of pasteurization is used, it is advisable to guard against having the temperature too high. From 165° to 170° F. is about right.

CHEESE VAT

A Cheddar-cheese vat of the ordinary channel-bottomed type is often used for the purpose of heating the curdled skim milk.

CURD KNIVES

Two kinds of curd knives are used. Both are made out of wire or metal strips fastened, half an inch apart, to a frame. One knife cuts the curd horizontally by being drawn lengthwise of the vat. The other cuts it vertically by being drawn, first, crosswise of the vat, then lengthwise. Thus the curd is cut into cubes.

CURD PAIL

When the curd is to be dipped from the vat, a curd pail, whose side opposite the handle is flat, is more convenient than the ordinary round pail, because the curd at the bottom can be scooped up more easily.

VAT WHEY STRAINER

The strainer commonly used is of metal, cylindrical in shape, about 5 inches in diameter, with a spout at the bottom which just fits the spigot opening. The strainer is placed in the vat outlet, which allows the whey to drain off, leaving the curd.

METHOD OF MANUFACTURE

RIPENING THE MILK

The object of ripening is to obtain the characteristic mild, sour-milk flavor and to develop the acidity necessary to coagulate the milk and bring about a separation of the whey from the curd when the coagulated milk (or coagulum) is heated. The temperature of ripening depends upon the time at which the cheese is to be made and the quantity of starter added.

Fresh skim milk should be set at a temperature which will produce a firm, smooth, uniform curd at the time of cutting. The ripening can be regulated by the temperature at which the milk is set and the quantity and kind of starter used. Experience soon will show the right combination of starter and temperature to be used for best results under existing conditions. A good, active, clean-flavored starter should be added at the rate of 5 to 10 per cent of the skim milk and the milk should be allowed to stand at a temperature of 70° or 80° F. This usually gives a smooth, uniform curd in from 6 to 12 hours.

Raw skim milk of good flavor, allowed to sour naturally, usually develops a well-flavored curd, but the probability of regularly obtaining a fine-flavored product is greatly increased by pasteurization and the use of a good starter. A starter of poor quality should never be used, because by introducing undesirable fermentations it does more harm than good; in fact, it would be better to depend upon the natural souring of the skim milk than to use a poor starter.

CUTTING AND HEATING THE CURD

The best time to cut the curd is shortly after it shows a firm and uniform coagulation, with an acidity of from 0.65 to 0.80 per cent, for at that stage a mild-flavored cheese is obtained and at the same time sufficient acid is present to give a clear separation of the whey

from the curd. The object of cutting and heating is to get rid of the desired quantity of whey and to remove much of the acidity, with the least possible loss of curd. The best method of cutting the curd is to use regular cheese-curd knives, described above, which cut the curd into fairly uniform cubes from which the whey can be expelled with but small loss of finely broken particles of curd passing through the drain cloth. To break the curd or coagulum with a stirrer produces too many fine particles of curd, which are easily lost in draining.

After the curd is cut, heat is turned under the vat, and the temperature is raised gradually to 115° or 125° F. At the Grove City, Pa., creamery, operated by the Bureau of Dairying, a temperature

FIG. 1.—Stirring the curd during heating

of 120° to 125° F. has given best results. Formerly a temperature of 95° to 105° F. was used for heating the curd; but when the cheese is made in large quantities it seems better to use a higher heating temperature and then cool immediately with cold water. Variation in the heat requirement depends upon the quantity of milk, the degree of acidity, the length of the period of heating, and the texture desired in the cheese. The curd should be stirred gently at frequent intervals (fig. 1) to prevent its cooking on the sides and bottom of the vat. A wooden rake may be used for this purpose. The texture of cottage cheese is controlled by the temperature at which the curd is heated, the length of time heated, and the extent of draining. Considerable variation as to temperature and time of heating and draining is found necessary, depending upon the condition of the curd.

Heating the curd to the temperature recommended above favors the rapid expulsion of whey, but care must be taken that the product does not become too tough and dry. Ordinarily 30 to 45 minutes are required to heat a 5,000-pound vat of skim milk to this point, at which time the whey is generally removed. The usual test for judging the proper time to remove the whey is to squeeze a handful of the curd; if the curd particles cohere in a gelatinous mass, the curd is too soft; when the mass becomes open and porous, and readily breaks up on being rubbed between the hands, it is time to withdraw the whey. Experience will serve as a guide to the right length of time and the best temperature for heating.

DRAINING AND WASHING THE CURD

When the heating has continued for the proper time, the free whey is drawn off from the bottom of the vat through a strainer, which prevents the loss of curd particles. The curd must then be more thoroughly drained to bring it to a sufficiently dry condition for

FIG. 2.—Cheese drawn to sides of vat, forming drainage trench in middle

salting. Draining was formerly done by transferring the curd to a drain rack lined with a cloth which served as a filter. (See fig. 5.) This has been largely superseded by the trench method described below.

When the rack is used, the curd is transferred to it, and the greater portion of the remaining whey passes through the drain cloth quickly. An occasional manipulation of the drain cloth, rolling the curd back and forth in the rack, hastens drainage. The extent of drainage necessary depends upon the texture desired in the cheese, the length of time the curd was previously heated, and the temperature of heating. If the whey is too completely separated from the curd the cheese may be too dry. To prevent this it is usual to wash the curd with cold water, which checks further separation, yet at the same time removes the whey already separated. Free whey in the finished cheese tends to create a strong sour flavor. With the drain rack two people are required to handle the cheese effectively.

The trench system of drainage is now more extensively used than the drain-rack system. In this case the various operations of washing, salting, and creaming the cheese are all carried out in the original setting vat. All the whey is removed before washing with cold water, unless there is danger of the curd becoming too dry, which is not frequent. If it shows signs of becoming too dry the cold water is run in immediately, before much of the whey has been withdrawn. After the curd has been sufficiently washed the water is drained as completely as possible, and the curd is piled along each side of the vat, forming a trench in the middle (fig. 2). This facilitates the escape of whey, in a manner similar to that used in the manufacture of Cheddar cheese. The purpose of washing the curd is to prevent it from becoming too tough and rubbery, and to aid in eliminating the whey. There should be little or no free whey in the cheese at the time of salting. The advantages of the trench system over the drain-rack system are:

(1) Less space is required; (2) drain cloths and special racks are eliminated, thereby reducing the cost of equipment and labor; (3) the curd particles are broken less and there is less loss of curd particles in the whey; (4) the curd requires less constant attention; (5) the curd may be salted and creamed while still in the vat, and packed directly from the vat into the tubs.

FIG. 3.—Cartons for marketing cottage cheese

SALTING AND CREAMING

When the curd has been drained sufficiently, salt is added and well worked into the cheese. The rate of salting is determined by the demand, some markets desiring a light-salted and others preferring a heavy-salted cheese. One and one-quarter pounds of salt to 100 pounds of cheese gives a medium-light salted cheese satisfactory to the ordinary taste. From 3 to 4 ounces of salt to 100 pounds of milk is about the right degree of salting, and perhaps may be a better basis on which to begin. It usually is advisable to salt rather lightly, allowing the consumers greater opportunity to prepare the cheese to suit their individual tastes.

The addition of 1 pound of sweet cream to 10 pounds of cheese greatly increases palatability, and is to be recommended, especially

when it is desired to build up a trade appreciating high-quality products. The cream is worked into the cheese with the salt. The additional cost of cream is small when it is considered that each pound of cream adds a pound to the weight of the cheese.

PACKING AND MARKETING

The ideal method of marketing is to pack the cheese in the small, single-service, sanitary, paraffined paper containers, of which there are many kinds on the market. (See figs. 3 and 4.) The containers are convenient for the dealer to handle, and are attractive to the

FIG. 4.—Packing the cheese in cartons

buyer. While cartons add considerably to the cost of marketing, the extra price obtained for the product in that form usually compensates for the additional expense.

Recently a 12-ounce glass jar, provided with a proper cap and fitted into a regular pint milk-bottle crate, has been used successfully by certain distributors in marketing cottage cheese. A container of this type may be readily washed, sterilized, and used again. Such a receptacle will not impart an objectionable flavor to the cheese.

Cheese to be shipped in bulk is best packed in butter tubs (fig. 5).

Cottage cheese always should be packed immediately after it is salted and should be marketed within a few days, as it is perishable and deteriorates very quickly at ordinary room temperatures. To insure marketing in best condition and to prevent unnecessary loss, it is important to have the cheese placed in the cooler or refrigerator

immediately after it is made and to hold it at a low temperature until disposed of. Freshly made cheese should not be shipped until after it has been well cooled, because the warm curd is in a condition favoring fermentation and deterioration. It is advisable, therefore, making shipment.

YIELD OF CHEESE

The yield of cheese, which varies from 15 to 18 pounds from 100 pounds of milk, depends almost entirely upon the amount of moisture left in the curd, and is controlled by the method of manufacture. The factors that influence the percentage of moisture in the curd and determine the yield are: (1) Temperature of heating curdled milk (or coagulum); (2) length of time curd is heated; (3) extent of draining; (4) physical condition of the skim milk after curdling.

FIG. 5.—Packing the cheese in tubs. Here the drain rack with cloths is being used

The physical condition of the skim milk after curdling often has a marked influence upon the resulting yield. A weak, unevenly coagulated curd, when cut, produces a large quantity of fine particles, much of which is apt to be lost during drainage.

The ideal cheese has a delicate, mild-acid flavor, and is a rather firm, smooth-textured product, free from any harshness or coarseness.

BUTTERMILK AS MATERIAL FOR CHEESE

Buttermilk has occasionally been substituted for part of the skim milk in manufacturing cottage cheese. Where buttermilk is employed it should be utilized as soon as possible after coming from

the churn, before any undesirable flavor develops. In general, the use of buttermilk as material for cottage cheese is not advised, unless the buttermilk is made from fresh, sweet, pasteurized cream; and then in quantities of less than 25 per cent of the total milk.

MAKING BUTTERMILK CHEESE

Creameries having only buttermilk from fresh, sweet, pasteurized cream can make it into a fair grade of buttermilk cheese. The curd may be precipitated from the soured buttermilk either by the vat method or by running the buttermilk through the ejector to heat it to the required temperature.

Because of the fineness of the curd in buttermilk, extreme care must be taken in heating to avoid breaking it up still finer. The amount of stirring required to bring the temperature of a vat full of buttermilk up to the proper point has a tendency to break up the curd so that a portion of it is liable to be lost during the process of draining. Running the buttermilk through the ejector heats it with the least possible breaking up of curd. By that method the curd is separated clearly and quickly from the whey and invariably rises to the top, facilitating a quick removal of the larger portion of the whey and making it possible to obtain the finished cheese in a short time. By means of a valve in the pipe leading from the buttermilk tank to the ejector and one in the steam pipe next to the ejector, the temperature to which the buttermilk is heated can be controlled easily. The proper temperature necessary for separating the curd clearly and quickly can be obtained readily by using a glass tumbler to catch samples of the heated buttermilk as it comes from the ejector. At the proper temperature the curd quickly rises to the top, and the whey is clear. By varying the temperature the proper degree of heat required is determined.

COST OF MANUFACTURE

Although the cost of manufacturing depends somewhat upon the cost of fuel and labor, it is influenced more by the volume of business. The table on page 10, obtained from records made in 1922, and showing averages for a two months' period when the volume of business was about 125,000 pounds of milk each month, gives a good idea of the approximate cost of manufacturing. The figures are based upon results obtained in the manufacture of cottage cheese in a commercial way at the creamery at Grove City, Pa., and, with the exception of the item of power, were obtained by making the proper tests to ascertain the expense of the different items. The labor represents the actual time of the men who did the work, figured at the rate which the average creamery would have to pay for the desired kind of help.

By making tests on the boiler to determine the number of pounds of water evaporated by 1 pound of coal, and by weighing the pounds of condensed steam required to pasteurize and later heat the milk to separate the curd, the cost of fuel was ascertained. The soft coal used cost \$4 a ton, mine run. The costs of power and cooling are estimated at figures considered sufficiently high to cover these items.

The quantity of water required to cool 1,000 pounds of milk was determined by measuring the actual water used to cool certain batches of pasteurized milk, and charging at the rate of 5 cents per 1,000 gallons.

Depreciation reserve was figured on the following basis:

Apparatus	Value	Probable life	Annual depreciation
Pasteurizing vat.....	\$750	10 years---	\$75
Making vat.....	225	2½ years--	90
			165

Taking 300 as the probable number of days the vat would be used gave a daily depreciation of 55 cents. The number of days the vat was used each month and the quantity of milk handled during the same period afford a basis for determining the charge for depreciation per 1,000 pounds of milk.

The following figures were used in obtaining the charge for interest on investment:

Apparatus	Value
Pasteurizing vat.....	\$750
Cheddar vat.....	225
	975

The interest on \$975 at 6 per cent amounts to \$58.50 a year. Twenty-six runs a month, handling 5,000 pounds each, gives 18.7 cents a day, which comes to 3.7 cents as the interest charge on 1,000 pounds of milk.

Estimated cost of manufacturing cottage cheese

Item	Cost per 1,000 pounds milk
Labor.....	\$1.106
Power.....	.265
Cooling water.....	.111
Depreciation reserve.....	.185
Interest on investment.....	.037
Total.....	1.704

The cost of the above items is figured on the basis of 1,000 pounds of milk because of the greater variation which would be shown when figuring on the basis of pounds of cottage cheese, owing to the variation in yield.

Figuring on the basis of a yield of 17 pounds per 100 pounds of milk the cost per pound of cheese would be \$0.01002, almost exactly 1 cent a pound, with no allowance for cost of package. These figures may be lowered with an increased volume of business; a decreased volume would raise them. When only a small quantity of cheese is made the regular creamery force may be able to do the work without any additional help, which would be an item of importance in determining the actual cost.

MARKETS AND PRICES

In cities where large industrial concerns employ foreign labor there is already a good demand for cottage cheese, and a satisfactory market usually can be developed in other cities or localities. The market demands and prices fluctuates considerably with the condition of the milk supply and the season of the year. An overabundance of milk makes more skim milk available for cottage cheese, thus tending to lower the price. As a whole the best market at the most favorable prices is afforded during the winter, with the Lenten season calling for the heaviest demands. A lighter market in the summer season may be attributed to a greater supply of available skim milk and to the fact that warm weather makes it more difficult for dealers to handle the cheese, and in some cases prohibits the trade. Dealers who make a specialty of handling cottage cheese assert that they are in position to buy and dispose of large quantities of the product throughout the year, the price to be governed by the quality of the cheese and the condition of the milk supply.

The Grove City Creamery began the manufacture of cottage cheese for the purpose of utilizing skim milk and buttermilk to the best advantage, and providing a market, at an attractive price, for the skim milk of those patrons who wished to leave it at the creamery. The business was begun in a small way, and because of other outlets through which the raw material could be disposed of to fairly good advantage no organized effort was made to develop a market that would take care of the increased receipts of skim milk. At Grove City the winter price received for the cheese without the addition of cream, packed in cans or tubs furnished by the buyer, varied from 4 to 6 cents a pound f. o. b. the point of manufacture. The wholesale price received for smoother-grained cheese to which cream had been added at the rate of 1 pound to 10 of cheese, and which yielded from 17 to 18 pounds per hundred pounds of milk, packed in the 12-ounce, single-service containers, was 8 cents a package net at the creamery, or at the rate of $10\frac{2}{3}$ cents a pound. The 12-ounce cartons, including the shipping box, cost slightly less than 2 cents apiece. When filled with cheese of good quality they retail ordinarily for from 10 to 12 cents. The demand for cheese packed in the single-service containers is from the grocery stores and meat markets in the near-by towns.

It is very desirable that a uniform quality of cheese be made at all times in order that the trade that has been built up may be retained.

SUMMARY

Cottage cheese made from a good quality of skim milk is a most palatable and nutritious article of food.

Good raw material is essential for making a good product.

The pasteurization of skim milk is recommended, because it insures a food free from all danger of disease-producing bacteria, and gives more favorable conditions for the manufacture of a uniform, high-quality cheese.

The main equipment necessary for making cottage cheese from pasteurized skim milk consists of a pasteurizing outfit and a channel-bottomed Cheddar-cheese vat.

From 5 to 10 per cent of a good lactic-acid starter is added to skim milk, then the milk is allowed to ripen at a temperature of 70° to 80° F. for from 6 to 12 hours, by which time it should be curdled. The curd is cut into cubes and gradually heated to 115° or 125° F. in 30 to 45 minutes.

When the whey has been removed, the curd is washed with cold water, drained, and piled along the sides of the vat.

The cheese is salted at the rate of 3 to 4 ounces of salt per 100 pounds of milk, and then packed in cartons or butter tubs.

Skim milk of good quality should give a yield of from 15 to 18 pounds of cheese per 100 pounds of milk.

The cost of manufacturing cottage cheese is low, depending upon the volume of business and the additional equipment necessary. Under ordinary conditions the estimated cost of manufacture, not including packages or overhead charges, is approximately 1 cent a pound.

An excellent method of marketing the cheese is in the small, single-service, paraffined paper containers, which are most convenient for the dealer to handle and which keep the product in good condition. Glass containers are also used.

PUBLICATIONS OF THE UNITED STATES DEPARTMENT OF AGRICULTURE RELATING TO CHEESE

AVAILABLE FOR FREE DISTRIBUTION BY THE DEPARTMENT

Bacteria Concerned in Production of the Characteristic Flavor in Cheese of the Cheddar Type. (Journal of Agricultural Research, vol. II, no. 3, reprint A-6.)

Cheesemaking Brings Prosperity to Farmers of Southern Mountains. (Yearbook Separate 737.)

Making American Cheese on the Farm. (Farmers' Bulletin 1191.)

Manufacture of Camembert Cheese. (Department Bulletin 1171.)

Manufacture of Cows' Milk Roquefort Cheese. (Department Bulletin 970.)

Neufchatel and Cream Cheese, Farm Manufacture and Use. (Farmers' Bulletin 960.)

Rediscovery of an Old Dish, Cottage Cheese. (Yearbook Separate 787.)

Trend of the Cheese Industry in the United States and Other Countries. (Department Circular 71.)

FOR SALE BY THE GOVERNMENT PRINTING OFFICE, WASHINGTON, D. C.

Comparison of Acid Test and Rennet Test for Determining the Condition of Milk for Cheddar Cheese. (Bureau of Animal Industry, Circular 210.) 5 cents.

Cold Storage of Cheese, Experiments of 1903-1904. (Bureau of Animal Industry, Bulletin 83.) 10 cents.

Colored Spots in Cheese. (Bureau of Animal Industry, Circular 24.) 5 cents.

Factors Controlling Moisture Content of Cheese Curds. (Bureau of Animal Industry, Bulletin 122.) 10 cents.

Federated Cooperative Cheese Manufacturing and Marketing Association. (Yearbook Separate 699.) 5 cents.

Study of Gases of Emmental Cheese. (Bureau of Animal Industry, Bulletin 151.) 5 cents.

Varieties of Cheese, Descriptions and Analyses. (Department Bulletin 608.) 10 cents.