TABLE
CROSS SECTION BOOK
ETC

KEUFFEL & ESSER CO.

DRAWING MATERIALS

AND

SURVEYING INSTRUMENTS.

NEW YORK.

CHICAGO. ST. LOUIS. SAN FRANCISCO. MONTREAL.

TABLES FOR EXCAVATIONS AND EMBANKMENTS.

DISTANCES FROM CENTER OF ROADWAY FOR CROSS-SECTIONING.

ROADWAY 18 FEET WIDE. SIDE SLOPES 1 TO 1.

FOR SINGLE TRACK EXCAVATION.

"Copyright, 1895, by Keuffel & Esser Co."

	0	.1	.2	.3	.4	.5	.6	.7	.8	.9	
0	9.0	9.1	9.2	9.3	9.4	9.5	9.6	9.7	9.8	9.9	0
1	10.0	10.1	10.2	10.3	10.4	10.5	10.6	10.7	10.8	10.9	1
2	11.0	11.1	11.2	11.3	11.4	11.5	11.6	11.7	11.8	11.9	2
3	12.0	12.1	12.2	12.3	12.4	12.5	12.6	12.7	12.8	12.9	3
4	13.0	13.1	13.2	13.3	13.4	13.5	13.6	13.7	13.8	13.9	4
5	14.0	14.1	14.2	14.3	14.4	14.5	14.6	14.7	14.8	14.9	5
6	15.0	15.1	15.2	15.3	15.4	15.5	15.6	15.7	15.8	15.9	6
7	16.0	16.1	16.2	16.3	16.4	16.5	16.6	16.7	16.8	16.9	7
8	17.0	17.1	17.2	17.3	17.4	17.5	17.6	17.7	17.8	17.9	8
9	18.0	18.1	18.2	18.3	18.4	18.5	18.6	18.7	18.8	18.9	9
10	19.0	19.1	19.2	19.3	19.4	19.5	19.6	19.7	19.8	19.9	10
11	20.0	20.1	20.2	20.3	20.4	20.5	20.6	20.7	20.8	20.9	11
12	21.0	21.1	21.2	21.3	21.4	21.5	21.6	21.7	21.8	21.9	12
13	22.0	22.1	22.2	22.3	22.4	22.5	22.6	22.7	22.8	22.9	13
14	23.0	23.1	23.2	23.3	23.4	23.5	23.6	23.7	23.8	23.9	14
15	24.0	24.1	24.2	24.3	24.4	24.5	24.6	24.7	24.8	24.9	15
16	25.0	25.1	25.2	25.3	25.4	25.5	25.6	25.7	25.8	25.9	16
17	26.0	26.1	26.2	26.3	26.4	26.5	26.6	26.7	26.8	26.9	17
18	27.0	27.1	27.2	27.3	27.4	27.5	27.6	27.7	27.8	27.9	18
19	28.0	28.1	28.2	28.3	28.4	28.5	28.6	28.7	28.8	28.9	19
20	29.0	29.1	29.2	29.3	29.4	29.5	29.6	29.7	29.8	29.9	20
21	30.0	30.1	30.2	30.3	30.4	30.5	30.6	30.7	30.8	30.9	21
22	31.0	31.1	31.2	31.3	31.4	31.5	31.6	31.7	31.8	31.9	22
23	32.0	32.1	32.2	32.3	32.4	32.5	32.6	32.7	32.8	32.9	23
24	33.0	33.1	33.2	33.3	33.4	33.5	33.6	33.7	33.8	33.9	24
25	34.0	34.1	34.2	34.3	34.4	34.5	34.6	34.7	34.8	34.9	25
26	35.0	35.1	35.2	35.3	35.4	35.5	35.6	35.7	35.8	35.9	26
27	36.0	36.1	36.2	36.3	36.4	36.5	36.6	36.7	36.8	36.9	27
28	37.0	37.1	37.2	37.3	37.4	37.5	37.6	37.7	37.8	37.9	28
29	38.0	38.1	38.2	38.3	38.4	38.5	38.6	38.7	38.8	38.9	29
30	39.0	39.1	39.2	39.3	39.4	39.5	39.6	39.7	39.8	39.9	30
31	40.0	40.1	40.2	40.3	40.4	40.5	40.6	40.7	40.8	40.9	31
32	41.0	41.1	41.2	41.3	41.4	41.5	41.6	41.7	41.8	41.9	32
33	42.0	42.1	42.2	42.3	42.4	42.5	42.6	42.7	42.8	42.9	33
34	43.0	43.1	43.2	43.3	43.4	43.5	43.6	43.7	43.8	43.9	34
35	44.0	44.1	44.2	44.3	44.4	44.5	44.6	44.7	44.8	44.9	35
36	45.0	45.1	45.2	45.3	45.4	45.5	45.6	45.7	45.8	45.9	36

Calculated by Julien A. Hall, M. Am. Soc. C. E.

Louis L. Ray

Harvard University

Dept. of Geology

Cambridge, Mass.

or

Smithsonian Institution

Washington, D.C.

If lost, please return —

June 1937

June 27

Visit of J. E. Upson and J. S. Perkins.
Rapid trip up the Snake la Poudre
to Home and Conal Creek moraines.

June 28 & 29

Visit of the Bryans

June 30

Remnant 1 mile NE of Bear Ranch.
Chukar with overlying (or inter-
bedded) limestone which caps
the remnant and forms talus
slopes down the sides. Patches
can be seen on nearby hills but
it is not continuous and there
is probably a lake deposit. Surface
of ls. is well pitted and has
some pot-hole like forms. From
this point the Sherman mts.
High Plains and the first level
below the High Plains show
immensely well. Boulders are up
to a foot in diameter.

High Plains surface east of Chukar
1/2 mile east of junction Highway
75 & 87 - caliche cemented gravel
with evidence of wind polish.
Sample of pebbles & sand at 1 ft
below surface, 6" max length of
pebbles or cobbles.

Driving to Site from Womerton one
can see remnants of H.P. to east -
then below that a well defined stage
on Simpson Mesa. This is the same
as that represented on high points
back of Thunderjig. Below
that are 2 well defined stages

and a valley phase. These tend to merge at the H.P.

Thus far no evidence of faulting of the Carbonate has been found. The layers seem to all be gravel capped. The material looks very similar to that found in the Antelope.

July 1

Traverse from camp on to H.P. and over to head of Spottedwood Creek and down canyon a back to Bear.

H.P. was very gently undulating surface with broad, shallow, grassy valleys.

Trend in general E-W. Following down stream there developed numerous small cutting and eventually were defined channels. The valley fill was dark sandy loams with layers of gravel. Character of valley changed with development of low terraces and spurs of varying heights.

As far as can be ascertained the 'g' sequence seems to hold. However later work will check this.

Near Brannigan Springs and Bear Ranch the Antelope is capped with 6' of lo. of lacustrine origin. It forms great talus blocks which make down the slopes. It is porous, looks like bacterial ppt. The surface weathers in a honey comb manner and shows excellent solution pits. 2 specimens collected and photo taken at Brannigan Spgs.

July 2nd

Five auto-

July 3rd

Photograph of surfaces between
Lumbermill and Log Cabin

Panorama at Log Cabin Store.

No drift - granite well de-
composed as in Winterstein Park.

Deerhorn Park - no evidence
evidence of glacial drift. Many
rounded to subrounded boulders of
various rock types with a deeply
weathered bed rock.

July 4 & 5

In camp writing on glaciation.

July 6th

Medicine Bow Mts.

Moraine east of Liberty Lodge very fresh with only a few boulders scattered here & there. Range from gravel to 8' diameter. Surface is very bouldery. Moraines downstream are left so bouldery, but are not as highly weathered as one would expect of Pre-Wisconsin. I do not think they are Pre-Wisconsin, but Early Wisconsin. Both are in the inner valley. Very youthful topography and no doubt the last ice of the Tertiary Range. This looks so good as Alaskan.

P.B. Seane can only get 1500 yds. from the peak in their finger lakes. Suggests an Early Pleistocene which has been on until very recently.

Atwood has 2 stages Wood & Pre-Wisconsin. Our Wood is north of junction of Mad Creek & Elk River. Large boulders located outside of the present valleys. He suggests they may represent a 3rd stage but possibly are only the "Pre-Wisconsin" which he tentatively calls Wood.

Plate 1 - Laramie Valley -
 # 6-7-8 View of the C. & P. valley at
 Hardsburg.
 # 9 View of the C. & P. valley at
 Hardsburg. # 10 View of the C. & P. valley at
 Hardsburg. # 11 View of the C. & P. valley at
 Hardsburg. # 12 "Some evidence" just
 north of Hardsburg.

At north end of Hardsburg Mt. the
 evidence that Hardsburg is a
 flood plain, 50' $\pm$, 90' $\pm$. There are
 several smaller intermediate terraces
 which do not seem to be continuous
 and higher up.

To all appearances the reasons for
 the cut up of the Hardsburg formation
 is due to the landslide which blocked
 the valley after the retreat of the ice.
 This has probably caused the formation
 of the original Chambers Lake and
 the lower terrace of the C. & P.

The moraine a little creek is
 covered with sand. The moraine
 complex covers almost the north
 end of both Hardsburg Mt. and
 large lateral moraine at the
 foot of the Mt. of Hardsburg.
 The moraine is well developed
 again.

There were not ventifacts found on
 the moraine.

There are a few moraines behind
 the moraine of a terrace of about
 50' feet. It seems to be
 comparable to the Hardsburg stage moraine.

Up the valley about 1/2 mile
 south of Hardsburg, the moraine
 of the present stage moraine.

A low west branch creek
 joins Laramie at the C. & P.
 through the old Laramie
 valley. It has been identified
 to form a box canyon.

Plate 2 - Tuff at
 Chambers Lake.

July 13

Picture #4 - Escarpment south of camp taken from the flats.

The flats which show so well on the topographic map are #2, covering the arroyo base (small floodplain) as #1.

Following up the creek to the camp there are well defined benches which are #3 along the creek. #4 is the top of the adjoining flat. #5 the two spurs at Bear Ranch.

Passing upstream through the narrow canyon, the stream to the west has the #3 merge into the broad slope below the hill west of camp. The eastern stream has removed the #3 entirely so that the flat immediately south of the camp is #2, into which #1 is being cut.

The small remnants of the #3 slope are reduced portions (low and rounded) of #4, which seems to be the Lindenmeier Valley. There

were boulders 6' in diameter in the wash exposed in the valleys. It was underlain by Pierre Shale and represents the #3(?) surface.

Photo #5 - Arroyo with Round Butte in background - direct. #1 floodplain into which arroyo is cutting. #2 the surface represented here by top of arroyo. #1 is 9' above arroyo. #2 is 26 feet ±.

July 14

Large boulders along hog-
backs. This is the #4 + #5
surface. It's top is covered
with coarse colluvio of sub-
rounded sandstone up to
3' in diameter - average .6-1".
From this point one can see
the #1 surface represented by
the arroyos and thin
flashed plains the #2 (lowest)
level surface, #3 represented
by hillocks and spurs above
#2, the #4 represented by
the lowest of the two highest
surfaces left and #5 the
highest.

Warren Sheep Camp corner
#2 surface along stream to
east. Further to east (1 mile)
is #4 surface which doesn't
show well on topo maps.

1 mile south Warren Sheep
Camp corner the #4 comes
close to the east side of road.
It is underlain by Pierre sh.
and has a gravel cap of about
5 feet, composed of ss. 1/8" max.
grains, fresh feldspar, quartz
and gneiss. Both vein and
colored granites. The #3 has
been completely removed

except for a low hummock to the
west and south.

The #3 to the west and south of
BM 5805 is held up by a ridge
of ss in the Pierre sh. and thus
may not be taken as true.

From a point near the Hummer Ranch
Spring one is on #4 and can look
across the valley to the #4 ridge on
the east side of camp road. Round
Butte and the cliffs to the SE and
those on the Eaton Sheet seem to
belong definitely to #5. The high
surfaces on the hogbacks seem also
to belong to #5.

Photos 9 + 10 - The #4 surface as it
surges from the mts. just south of
Boulder Creek (valley in foreground)
This is irrigated and good farm-
ing land.

Butte at roadside at Jack Fork #4
and covered with ss blocks, granite
flint + feldspar.

Photo 11 - Ludlumier Valley camp
from road in.

July 15

At Waverly the #4 becomes a series of remnants and the #3 is a rolling upland. #2 is floodplain in this region.

The ridge along eastern side of Weld Co. seems definitely to be #5. #4 is below it on the west side along the Boxelder.

This ridge (like most of the surrounding country) is covered by wind blown sand. Bedrock is Pierre sh. and beds of Pierre sandstone.

In road cut at crest of ridge on Wellington - Home road there is exposed approx. 15' of gravel and cover of 5' max. of wind blown sand. No bedrock exposed. Gravel is schist, rhyolite, granite and sandstone gts. Gravel up to 18". Not much caliche. (Photo #12).

Mesa in T9N, R67W, Sec 10 - Antelope (Mather), with at least 20' gravel cover and wind blown sand and ventifacts. This stands above the #5 surface - possibly because of the more or less well cemented character of the rock.

Coming down the Indian Springs Coal Mine Hill one passes from

the distinct #5 to a dissected #4. This fits in pretty well with the #4 surface at the mt. front.

All the #4 surface is covered by a thin layer of sand which is a recent deposit containing #4. The surface is a slightly (nd, all) with a thin layer of sand containing a few fish bones. To the south, the surface is rather incomplete remnants of the #3, a slight remnant of the #2 and the river floor. The surface is slightly higher to the east and north.

The #4 surface is a slightly higher than the #3 surface. The #4 surface is a slightly higher than the #3 surface. The #4 surface is a slightly higher than the #3 surface.

The #5 surface is a slightly higher than the #4 surface. The #5 surface is a slightly higher than the #4 surface. The #5 surface is a slightly higher than the #4 surface.

#4 surface is a slightly higher than the #3 surface. The #4 surface is a slightly higher than the #3 surface. The #4 surface is a slightly higher than the #3 surface. The #4 surface is a slightly higher than the #3 surface. The #4 surface is a slightly higher than the #3 surface.

The #5 surface is a slightly higher than the #4 surface. The #5 surface is a slightly higher than the #4 surface. The #5 surface is a slightly higher than the #4 surface. The #5 surface is a slightly higher than the #4 surface.

Photo is between Dubois and Soldiers Canyon. It is not clear that is good.

At Soldiers Canyon below 2nd bench on plate which is a slightly higher than the #4 surface. The #4 surface is a slightly higher than the #3 surface. The #4 surface is a slightly higher than the #3 surface.

July 17
 Photo is between Dubois and Soldiers Canyon. It is not clear that is good.

Photo is between Dubois and Soldiers Canyon. It is not clear that is good.

Photo is between Dubois and Soldiers Canyon. It is not clear that is good.

Photo is between Dubois and Soldiers Canyon. It is not clear that is good.

On the gravel capped hills N-W of
Billings the gravel has much talus,
but is abundantly laminated with
gravel, etc. Up to 2.5' - just
above the rounded. Below it is
a well developed #1 + #2. The #2
I mistook last year for #3.

Picture of the #4 spot cut out
off from north of (La P. Photo #7)
#3 + #9 - weathering etc. in the
upturned cut ss (Tentative?)

Tentative thought to correlation:

The surfaces all seem to slope away
from the mts. and toward the major
streams. Thus all the surfaces are
lower at the mouth of the (La P. than
in the interstream areas. At the
mouth of the (La P. canyon there are
excellent spurs of the #4 surface,
about 250' above the stream. This is
probably what V.T. would call the
Oroville surface - the ~~top~~ surface -
upper cycle of weather. It is a pre-
maturely terminated canyon cutting
cycle. There has been subsequent to this
the younger, narrower inner canyon.
My #5 may represent the Mt. Morris
Basin which V.T. correlates with
the Alford Cycle. This seems to be true,
but it is not well represented along
the (La P.

Now - my Oroville may be
correlated with the Pre-Wed. and
is probably Illinoian. The Alford
or #5 is this early Pleistocene
#6 is early Pleistocene or late Plio-
cene. #7 - the high Plains surface
is Pliocene.

At the mouth of Pandee Canyon the
#3 is a high gravel and a notch
#2 is full material which from the
floor of (Pleasant valley (Billings).
#1 is the present floodplain.

Looking on north valley with foot above
Billings (Tentative correlation) canyon and
can see excellent #4 spurs and what
appear to be #5 at mouth of Billings

Sunday July 17th in camp.

July 19th

Climb to the high pinnacle just east of the moraine. This pinnacle was associated with a large mass of schist and granite. The granite shows typical rounded weathered blocks. The sides of the pinnacle are of talus, with stream bed of rounded material only at high on the moraine. At a distance the drainage from the moraine is a series of small streams on the rock island.

An interesting find on this pinnacle are the apparent marks of lightning striking them. The marks were to be seen on the rock. The type of fossil bacteria seems to be the same both on the granite and the quartz. Has this ever been described and is a new mineral formed?

Photo 10-11+12 looking down on the moraine - showing the secondary rounded ridge running across it. This would represent a slight advance.

Climbing into the col just across the river from the Horse moraine one finds an old high level channel of the S. L. R. which runs from 1.5 miles west of Horse moraine to Ring Ranch. It is approximately 500 above the present stream & no doubt correlates with the Alford Stage (?). The Horse moraine is represented by lower spurs about 500 feet above the stream. This old valley was narrow and contains weathered boulders of the local rocks only, as far as I could find. It has been dissected with the reduction of the river channel and by the tributary streams.

On the north side of the highway there was found one small and polished stone & water wearing on the 90' bedrock outcrop. Found on this. Collected here Tertiary ign. rock with feldspar etc. Rhynchonella found on the Horse moraine.

There may possibly be another one of these old valleys at east end of Horse moraine at edge of map.

July 20 -

Lateral moraine - south S. (La. P.)
2 miles upstream from Home.

Looking toward Home one sees a broad
valley flat in which the stream meanders
broadly and has a well developed
flood plain (the #1 surface?). Above
that is a well developed gravel
terrace (#2?). Covering the terrace
are thick fan deposits, as from
Peterson Creek, etc. Talus deposits
in some places fill in the back
portions of the fans with coarse
boulders which are not common
on the surface of the fans.

See smoothed surfaces can be
seen on the opposite valley wall
up to at least 500+ feet.

On the north valley wall above the
old channel cover the same 3
main surfaces 9300±, 9800± +
8700±. There may have no real signi-
ficance.

The lateral moraine slopes from the
high bedrock point to the west and
is about 700' (average) above the
river. It is thought to have formerly
covered and closed the entire valley
but to have since been removed through
erosion, part of the debris forming

the large fan at the base of the slope.
Then are boulders up to 10' feet in
diameter on the surface. Some are
split through weathering, others
still show signs of a polished surface.

In the valley to the rear of the moraine
is a well developed terrace, sweeping
out from the moraine. It is com-
posed chiefly of fine gravel which
has only a few large boulders on
the surface. It must have been
formed as a lake deposit when the
ice and moraine dammed the
valley.

On north valley wall in draw
between Roaring Creek + Peterson
Creek is the summit of either a
terrace or lateral moraine which is
at approx. the same elevation as the
one on the south wall.

Traverse up the S. La. P. to Williams Ranch.
Williams Ranch is located on a ex-
cellent terrace 10-15 feet above
the river. Terrace slopes gently to
river.

In NE ¼ Sec 30, just SE of Williams
Ranch there are two excellently preserved
terraces, one measured at 12' higher
at 30'. The occur on both sides of the
river, but were measured on the
south side. They are underlain by

gravel (2' to 3' size) of granite, schisto, etc. no volcanic noted but they must be present in small bits. Portals of these terraces are covered by alluvial fans.

C Across river from Williams Ranch a large and irregular laterite moraine, also good 52 foot terrace. A small gravel patch which may represent the 50' terrace (it was too fragmentary to be worth measuring). The 52' terrace measured at bridge across river at Williams Ranch. The lower terrace is only 8 feet at river bank.

D 1 mile west of home the S. La P. has well developed floodplain of dark alluvium which is 18' above the water level, when observed. Above this there is a good terrace at about 11 feet and another at 29' and another at about 39 feet. These measured. All terraces S. La P. relatively smooth surfaces and are of gravel.

/// Check till across from latitud.
moraine east of Williams Ranch.

E Terrace approx 35' above water ^{8/4} with most of 2 immenent. This right along edge of the road, near the valley wall. When it extends to the center of the valley it becomes reduced to the 25' level. Underlaid by medium well rounded gravel with one or two boulders 10' in diameter.

Walking toward home from Rugh Ranch.

On north side of river at Rugh Ranch there is a well developed 10' terrace which was not measured.

25' terrace (measured 24') ^{3/4} mile west of Rugh Ranch. Boulders unusually large (up to 4' max diameter) - but this is along valley wall. 10' surface poorly preserved on south side of S. La P.

23' terrace, north bank, ^{1/4} mi west of Black Hollow.

Good 10 ter. (unmeasured) under Purple Rock, ^{1/2} mile west of Idlerville.

The top of the hill is 70 feet above the water level. The hill is composed of a soft, silty material, and the top is covered with a thin layer of vegetation.

The hill is 100 feet in diameter at the top. The slope is 1:1. The hill is composed of a soft, silty material, and the top is covered with a thin layer of vegetation. The hill is 100 feet in diameter at the top. The slope is 1:1. The hill is composed of a soft, silty material, and the top is covered with a thin layer of vegetation.

On the side of the hill, there is a small stream. The stream is 10 feet wide and 1 foot deep. The stream is composed of a soft, silty material, and the top is covered with a thin layer of vegetation. The stream is 10 feet wide and 1 foot deep. The stream is composed of a soft, silty material, and the top is covered with a thin layer of vegetation.

The hill is 100 feet in diameter at the top. The slope is 1:1. The hill is composed of a soft, silty material, and the top is covered with a thin layer of vegetation. The hill is 100 feet in diameter at the top. The slope is 1:1. The hill is composed of a soft, silty material, and the top is covered with a thin layer of vegetation.

The hill is 100 feet in diameter at the top. The slope is 1:1. The hill is composed of a soft, silty material, and the top is covered with a thin layer of vegetation. The hill is 100 feet in diameter at the top. The slope is 1:1. The hill is composed of a soft, silty material, and the top is covered with a thin layer of vegetation.

The hill is 100 feet in diameter at the top. The slope is 1:1. The hill is composed of a soft, silty material, and the top is covered with a thin layer of vegetation. The hill is 100 feet in diameter at the top. The slope is 1:1. The hill is composed of a soft, silty material, and the top is covered with a thin layer of vegetation.

The hill is 100 feet in diameter at the top. The slope is 1:1. The hill is composed of a soft, silty material, and the top is covered with a thin layer of vegetation. The hill is 100 feet in diameter at the top. The slope is 1:1. The hill is composed of a soft, silty material, and the top is covered with a thin layer of vegetation.

The cirque at the right (from which Long Draw ice moved) is the largest seen. At the entrance to the valley from Long Draw is a well developed moraine (the early one). The moraine is not high (335) but is very distinctive, with large boulders of Tert. volcanics and Puc. E. No obsidian seen on moraine, which is grass covered. However, obsidian was found in the gravel deposits in the valley between the 2 moraines. The finding of this obsidian leads to the belief that report of a Tert. flow, which has been exposed in the Trap Creek and the Long Draw cirques. No obsidian was found over on Joe Wright Creek. The Tert. volcanics seem to be resting on the Puc. E. in such a way that the upper portion of the cirques are Tert. and the lower portion is Puc. E.

The Long Draw cirque is compound showing 3 stages

It is the best developed of any seen.

Back at Joe Wright Creek - Simon Bell. One on hillside one finds float of basaltic quartz & columnar etc. cavity filling. Here are clues to the things known in the sand but the John Zimmerman volcano. A piece of basaltic quartz given to me by Miss Agnes Zimmerman. This all seems to tie in with the idea of recent volcanic activity in the mts.

Is the Joe Wright Creek moraine an a moraine? No obsidian found here, nor any found in the creek from Zimmerman Lake.

July 23 -

Collecting 5 samples of sand and gravel from the dome moraine.

Back at camp in evening.

July 24

Repair auto

July 25 -

Photo #1 - 6' gravel on Brule wind blown material on top with ventifacts on surface. RR cut (U.P.) 2 mi. S Colorado - Wyo. boundary. This the #5 surface. At break in slope to lower surfaces, a concentration of gravel. (3 mi S W direction)

Photo #2 Erosion remnant of ss. in Brule fm., 2 mi east of Carr.

Photo #3 - Another erosion pinnacle at same locality.

Sandstone highly cross bedded and friable (crumbly) with iron concretions + iron stone on the surface.

Moat around the pinnacle with steep wall to W, NW, + SW and gentle slope to east, showing prevailing wind direction.

Ventifacts found around sandstone.

Photo #4 Looking E High Plains from the top of Simpson mesa. Simpson mesa covered with wind blown material and gravel showing in some instances evidence of wind abrasion. Surface very flat. Edge shows characteristic heavy gravel slump. Gravel of gneiss, quartzite, granite, schist, gneiss, etc.

Photo #5 View east along Brule Chalk Bluffs.

Photo #6 Arkane capping Brule along Chalk Bluffs. Arkane a crossbedded conglomerate. The westernmost of the two frontal hills.

July 21

(Coarse conglomerate, loosely cemented with lime on upturned Pierre sh. just east of Drumacore Ranch spring. Contains boulders up to 12 inches of ls., granite, etc. Many boulders of granite. Thickness about 10 feet. Sample taken. #4 Surface.

Photo #7 View west from Drumacore Ranch valley showing the #4 surface (in background) truncating dipping old beds. The background slope is Mother's Alford.

Photo #8 - #4 surface joining the hogback and 1 mile south of Drumacore Spring. Boulder Creek in foreground.

Coarse gravel on #3 at crossing (bridge) of Boulder.

1/2 mile below Drumacore Ranch there is #3.

Ask Bryan's opinion.

Photos 9 & 10 Limermore Mt. & Valley showing Limermore & Alford layers, so much as you wish.

The Alford surface is dissected and the granite deeply marked with residuals.

Travel on Crittendon 2 1/2 miles NW of Limermore.

Prairie Divide largest and most beautifully developed of moraine seen in this country.

July 29 Ft. Collins & south.

South side Fossil Creek at hog-
backs, excellent #3 surface
reaching hogback at about
5250 ft. But captured
beds. Thin gravel cap of medium
to coarse cobble encased fine
and scattered sedimentaries, sandstone.

On the north side of Fossil Creek
are at least 15' of stratified material
with no bed rock showing. Much
interstratified with sandy and
caliche cemented grains of small
pebbles. Some 3" blocks 4" in diameter.
Material angular to subrounded.

Lowland Creek —

See Sec 23, T 6, R 69 is 80' above
the #3 surface which is behind it.
It is held up by sandstone with
wind blown sand on surface.

See map for locations

Behind Table Mesa there are 3 sur-
faces. One = Table Mesa surface
A lower #3(?) and the other
just plains with which the stream
is cutting. Table Mesa is probably
the same as Lowmore.

The Sunbowl Hill is thought to be
#4 — and a dissected remnant of
Table Mesa. It is underlain in part

by sandstone (Pierre?) and
covered by wind blown sand.
Across the valley of Boulder Creek
there is its continuation. To the
west near the hogbacks is a good
spur of the #3. Below it are
irregular #2 and #1.

Dunbar Hill shows some
well rounded and caliche
cemented gravel under the
heavy wind blown mantle.

July 28

Return to camp with Billings

July 29 + 30

Trip to North Park

July 31

Frank and I mi. E. Round
Butte sandstone outcrop on
left face. Contains large
stone concretions. Buff and
medium grained. Looking at this
variegated shales and sandstones
these are Ganamie. Thickness
here about 500 feet, for there is
an unconformity at the top
of the Ganamie and resting on it
is the Arkose, which at
places is coarsely conglomeratic.

Photo 2 - The unconformable
contact of Ganamie + Arkose.

Good example of channeling of con-
tact between the Arkose + Ganamie.
Photo 3 showing this channeling.
On west flank of Arkose there
is also a secondary gully.

Round Butte - dip $65 \pm 10^\circ E$
Strike $N 30^\circ E$

At Round Butte there is a fault
which may be a normal fault. It is
located on a fault where beds of
various ages (Pike, Fort Verde, etc.)
brought to the surface, have
been broken, channelled, and
covered by the Arkose.

The material on the top of R.B. seems to be Grikaree and is not a definite formation as Mather says, for it is similar in every way to the Grikaree, except for color. Consolidation, size and character of material are the same. The channelled surface is of extreme importance.

The structure has been interpreted as a fault by Mather.

Camp Flats Profile

Start BM #1 as base

Sta I Dist $\angle$ Reading HI 3.9

1	300	40° 22'	5
2	130	33° 42'	0
3	240	24° 30'	12
4	300	22° 40'	12 Bottom of arroyo
5	240	25° 5'	10

Sta II 850 31° 42' 12 HI 3.4

6	400	27° 48'	3
7	280	25° 55'	12
8	520	30° 20'	4

From B.M. at camp the profile comes down across the eroded Bull to an arroyo, then across what is thought to be #2, with residual Ruallo of #3 to top of hill of #3 or 4 (presumably #4). This has much gravel cover but a lot of material of the gray Arkane conglomerate.

Sta II HI 3.3

9	190	16° 57'	12
10	215	15° 15'	12 Bottom arroyo

11	240	23° 50'	12 } Flat
12	500	24° 57'	12 }
13	620	24° 39'	12 Bottom arroyo
14	650	26° 53'	12 Top arroyo

This last arroyo cut into the low level Arkane which lies on the flanks with a well developed concretion. The Arkane highly eroded and to gravel cover as beds and lenses in the Arkane which must be removed.

Sta IV 850 28° 38' + 15' 12 HI 3.5

15	720	27° 50' + 15'	12 Gully
16	660	28° 15' + 15'	12 Hill Top

17	560	27° 52'	12 } Flat
18	420	27° 30'	12 }

19	200	28° 37'	12 (w edge of flat for 100')
20	160	29° 20'	12 Beginning of flat
21	540	28° 54'	12 Flat -

Sta V 550 31° 36' 4 " HI 3.5

22	500	29° 50'	12 Flat still
----	-----	---------	---------------

Sta VI 400 30° 20' 2 HI 3.7
Flat at edge of arroyo

23	130'	-2° 33'	12'	Bottom average
24	320'	0	5	Top of "
25	520	+17'	0	Bottom slope
Sta VII	450	-29° 35'	12	HI 3.5

Slopes more along the bottom
Sta VII + 26 2 26

26	300	40° 45'	10	Top of rise
Sta VIII	480	+26'	5	#5 flat HI 3.7
27	150	0	9.8	slope down
				side of flat to back in slope.
Sta IX	640	+5° 15'	10	HI 3.7

The flat bottom of this valley is dissected by intermittent or discontinuous average cutting.

28	480	+2° 38'	3	
29	400	+3° 20'	3	} up slope #5
30	600	+5° 15'	3	
Sta X	380	0	8.4	HI 3.2

Between 30 & X is a depression due to later erosion, but with no significant. #5 high on Bank, gullies filled with wash.

31	320	-10° 12'	12	
32	560	-9° 5'	12	
33	600	10° 10'	12	Grassy bed

34	800	2 + 10'	0	HI 3.6
35	460	-4° 10'	12	Flat (on bank)
36	380	-8° 20'	4	Average bottom
37	240	-10° 6'	2	Flat as 35
38	160	-14°	7	

		25' west "34" drop-down to flat		
	# 39	0	12	
39	200			
40	980'	+40'	0	

25' to north of 40 is a hill rising approx 20' - about the surface which is represented by 40 (#39?). This is cut and fill, hill has gravel.

Sta XI	380	+1° 25'	2	HI 3.6
--------	-----	---------	---	--------

Aug 11th - Cocula Point

2nd point at 1/2 mile (NE corner Sec 7 - T 7 R 19) is surrounded with a wall diameter of 10". Composed of material of horizontal strata, mica schist, with ls., ss (red + white) and gneiss. Some rocks not important. The material is mostly derived locally from the red, pink and grey gneisses.

Continuing around corner to creek in Diego Lopez going down to first plain of the Chila P. much gravel has been thrown out on the collection of ditch. It is mostly red, green (4") and predominantly pink.

Top of hill just east of Thompson's is covered with red, green and decomposed gravel on bedrock. It is mainly pink, but has some green and red. At least 10' of gravel. This is mostly about 3' and must be #4.

At bottom of the first plain (1/2 mile) there is a small hill. This is composed of well rounded gravel in pink, green, and red. The surface is gravelly.

Between Devil's Canyon + 1/2 mile a water well is being drilled in the valley floor, down to 100 ft.

Detailed log of Chila P. from Stone Plains

T 8 N, R 91 W, Sec 7 start

1 Hand climbing up to spur SE road corner of about 300'. It is with nothing that there is no gravel on this spur. From view up and down valley, it would at first seem that there was no accumulation of gravel, but when considering slope, weathering, etc. it would seem that at 400' + 700' there are a series of spurs which may be the same. A lower series which seems to be at about 150' ± is seen upstream on N. bank.

(300' was to be in spur, which has an apparently narrow top of about 5').
Side slopes are talus covered. Red schist with pyroxenite.
Across river there is 20' ± rock bench and 6' ± floodplain gravel.

2 As we round spur going down - there is a small spur of coarse well rounded gravel covered with talus, at about 30'. The top is not well exposed. (I think this was measured last summer.) 30' lands in river top on one stream and is low level at 30'. Across

river here is broken up by a series of
about 50. Coarse rounded boulders
below. There are two species. Bed
rock under water very fine. They
are grayish topped. (North side)

4 River running north up around
spit (400+) on the north
side. SW 1/4 Sec 5.

5 At apex of bend there is gravel and
sand. Below fine gravel material
shown to Bryan. Photograph #5
Above and below of the bend
top slope there is a spring of
groundwater.

When rounding the
point there is
exposed, well rounded gravel
at apex of bend 40' above the
stream. This on rock bench
on which the bedrock shows
water running and rounding.
South bank NE 1/4 NW 1/4 Sec 5
this is a narrow where there
is very little exposed, either
gravel or low spurs.

6 Tunnel - at point where stream
is constricted there are irregular
pools and water runs surface
30 to 50' above stream. Numerous
rock pinnacles showing back of
gravel. Topography

shows the old higher broad valley
at about 400-600'.

7 Out of narrow at Thompson's Run
between Sec 4 & 5. River. At T.R.
picture # 6 of talus showing tendency
toward bedding.

8 Mouth of Watsons Gulch - side.
There is what appears at first to be
a terrace level I think it wash
and talus. Looking up and down
stream one can see the levels of
spurs - seem to be about 700' -
400' + 150 to 200'. Good flood-
plains downstream - both sides at
1-10 ft. 3/4 mile east Watsons
Gulch there is on north side a
15' terrace, and good 300' spurs.
30' terrace covered by talus,
then dissected (north side). This
not measured. It has 20' talus on
it and is on 8' exposed bedrock.

9 20' gravel covered by talus at
stream bend (see sketch),
between sections 3 & 4.

10 15' gravel with talus cap (middle
of Sec 3).

11 "plains" E pk Sec 3. NE from East.

12 Hewlett's Gulch - E side of
in north bank. 90' hand leveled surface.

covered with talus. Measured
 29' but must be to top of
 till from talus. Small amount
 on side of La P. at same
 elevation. In who. of last year.
 Many appear this winter.

- 13 Timberline spurs east of Hault 1/4 to
 1/2 mile (N.E.) which must be 200'
~~100'~~ above river. One on side
 between Rainbow Ridge and
 Hault. Hault 162' and
 is gravel capped. The surface
 is covered with spurs and
 Hault 162' and with
 spurs extending to the south of
 La P. This surface is SW 1/4 Sec. 1.
 12' back below the surface.

- 14 South side gravel point 23'
 gravel bench of coarse, yellow
 sand and gravel. High red
 bench on N. side which seems
 to correlate with the 162 surface
 below it a 15' terrace of gravel.

- 15 Good high surface on east 1/2
 Sec. 1. Approx 12' above river
 river. Talus covered. Same as
 terrace at Hault on S side, covered
 by fine talus - mud brown.

- 16 Spur level at 225' ± on S
 in E. pt. section 1. Numerous

are abundant spurs up and down
 valley.

August 12
To Canyon -

Ditch dug in Ft. Collins
tell me one has to go 12-15' in
the town to strike gravel.
Cover is fine alluvium.

Remnants of great old allu-
vial fan off Hill 14 mile N
of Lake. No bedrock.
Material is predominantly
angular and local block
material. This seems to be derived
from Soldado Canyon where
there is good gravel previously
described as #3. Some red ss.
ls. and granite.

If this is true the talus material
should interfinger with the allu-
vial gravel. It
is doubtful if the
tributaries even cut
as low as the main
streams. They were left as hanging
valleys and probably built up
alluvial cones, etc. If this be
true the #3 surface probably
never came into the headwaters
of all except along the main
streams.

Continuing north to where road
enters Bellvue valley the surfaces
seen there and pictured I believe

think to be dissected talus cones.
There are no cuts through these which
would show if they lie on gravel.

17 On high hill in front of Bellvue
anticline NE 1/4 Sec 25 there is
good gravel, coarse, well rounded
and the greater portion fine. It is
about 140' above river and is un-
derlain by bedrock. However, from
the slope it seems to fit in with the
#4 surface previously described at
mouth of Soldado Canyon. #2 & 3
seem to be developed below it.

18 Sunday Water Works - In Sec 14, 15 & 23
the high points are on bedrock and gravel
capped. They are 100' + above the river.
Gravel is typical, coarse, well rounded
fine. Much clay and silt. It
probably represents a
There is a well represented but
dissected surface at the corner
#3 gravel (30-40') which is good
gravel coarse and fine, red slump which
contains fragments of gravel. It
is possibly talus cutting across with
stream gravel.

19 On hill at right in SW 1/4 of 14 there is
what may be bedrock. In lithology it
is typical but in position it is wrong.
It seems to be either interbedded with
or in a pocket in the red Mountain fm.

20 At mouth of canyon (N5) there is small gravel patch on bedrock. This was then covered by debris in 1936. Does it represent 3 (or 4) or neither? Has it any significance? There are well developed rock spurs on either side of the river. An excellent one at 550'. Others at 150', not measured, 500' & 700'.

I think the 150' is #4
the one (the measured) #3

21 At river bend (Sigs 9 & 10) there is good gravel terrace, but it is hard to get river level, as it has been dammed. Terrace about 18-20 feet, coarse, well rounded. Part. In bend there is good low floodplain at about 1-2'. At bend banked up the spur on N5. It is about 225' and falls in with a whole series of terraces are around but very irregular due to work of cutting back. No gravel seen. Bedrock is visible all over these surfaces. Where it outcrops very poor weathering pit formed. Bedrock is lenticular from bedded schist.

Above this are 2 more series of spurs at (roughly) 350 and 500 to 600 ft.

22 Around bend in Sigs 9 on N5 a good coarse well rounded gravel mainly Pz at 18 feet covered with talus. 55 river terrace at 15 feet above stream. Same gravel. Photo #9. This fine material is the same mentioned last year. Why is it without more coarse material. Could the strati-
fication be real?

23 Along straight stretch in Sigs 9 on N5 (33) typical gravel at 12' covered by 4' talus.
North end Sigs 9 N5 (ask Bryan about gravel.)

24 Sigs 4 where rd crosses river there is on 18' bedrock shelf with 12' good gravel on it. Photo 8. The gravel shows a slight hint of imbricate structure, the gravel facing downstream. Low 8-10 foot terrace at river.

25 Upstream at sharp bend get a 36' foot terrace and high spurs at 174' and 282' ±. There is one higher surface, not well defined. 282' seems to fall in with 250' of Sigs 16. Minor ones fall in with 174'. No gravel on these.

26 Upstream for 1/2 mile there are scattered remnants of 20' gravel covered with talus. Both sides.

27 Ft. Collins Water Works.
North Fork enters. No terraces which are thought significant. Dam in river. To edge of Ft. Collins sheet. No terraces of significance. Gravel on N. bank in Ft. Collins Park which has a probable depth of 12' ±. This continues upstream for 1/2 mile. Just east of center of Sec 5 there are bedrock spurs 80 feet above the stream. No gravel on them. High spurs at 200' ± (not measured). 80 measured on SS + silt across.

28 Coarse gravel NS SW & NW of Sec 5. Thickness estimated at 30' ±. Another spur in bend which seems to be accordant with the 80' on just described. High spurs unmeasured at about 200' ± both sides of stream.

29 At bend (SS) gravel terrace at 24 feet.

30 Continuing into Sec 31 the high spurs are 200' ± continuous. On NS a NW gravel terrace at 8-10'.

SS - gravel 12' in thickness on 30' of bedrock. Common, typical. This is estimated. Sand, silt - stratified with the gravel.

Three taken to pt. where ended previously by climbing spurs.

Friday August 13th
Continuing detailed log upstream
from Stone Prairie Landing.

- 31 500' west of S. P. road there is an 80' a very coarse boulder bank, levelled at 48 feet. Some boulders are 4' in diameter and are well water worn and polished. This has the appearance of being laid down in a swiftly flowing stream and must correlate with the Home Stage. There is also much fine gravel in this deposit.

Note - It looks as if there may be a 90' terrace, but it may be 200' to 50' instead.

Spread out on this gravel is a great talus cone, which is where it reaches the surface. Could it have been pre surface?

At about 150' ± there are numerous sand dunes, especially 1/4 mile upstream NS.

Gravel terrace thought possibly to be on a bedrock bench of 20 ± feet.

The 150' benches upstream (NS) are a bedrock with about 20' gravel on top.

This gravel seen with field glasses only. It is coarse and only last-avalanche.

- 32 1/4 mile downstream from Sheep Mt. 50' the 50' gravel covered by talus, no same gravel resting on bedrock. There is about 15' ± of bedrock. This shows well below the 150' surface. On Sheep Mt. there are good signs at an elevation of 350-400 (by estimation).

- 33 Stevens Gulch - good gravel at 78' levelled on 55. Starchie along for about 500 ft. Now it is about 150' there is break in slope with sparse. Not measured. Also a 10' floodplain on NS.

- 34 Narrows around Sheep Mt. No gravel except at Bridge where there is small outcrop at 20' feet covered by talus. Only 3 feet gravel exposed and it is fine - fine diameter. Some 100' ± there are some large angular blocks which were apparently derived locally.

- 35 In Narrows there seem to be some 150' & 200' wide spurs. Some water rounding of the bedrock. There is one small patch of gravel on NS at about 25' above water. This measured last year. At the middle of Sec II.

At the end of the river stretch, there is a ± 300' spur (unmeasured).

All the full etc. in the river must be caused by it to aggrade for in several places there are drowned trees and tree stumps in the channel.

- 36 At road bend NW $\frac{1}{4}$ Sec 2 there is 54' approx of gravel, also a 35' rock spur. In the very coarse material in this gravel which is angular to subangular.

- 37 Broad open valley of section 2. Terrace with bedrock beneath as pictured last year. Col on S. S. between 300 & 400 feet, but near 300.

- 38 Terrace on S. S. at 18 and another not measured at approx 50'. It and seemed to break in to the spur at 148'. There seems to be a number of spurs at 150 - 170 feet. Continuous gravel on bedrock at 50'.

- 39 Elk Horn Creek. See last year notes for description of terrace to the west 300 ft.

- 40 At bend in river NE $\frac{1}{4}$ Sec 3 there is a 10' low terrace and a 30' terrace of coarse boulders (picture 1932) which rests on about a 15' bedrock ledge.

- 41 Mouth of Little South, N. 25' handwashed gravel terrace.

- 42 Ft. Collins N.W. Park. See last year notes for terrace measurements.

- 43 Bennett Creek - coarse gravel with waterworn or N.S. up to 30 feet above stream (h.d.) Large boulders of talus rest on vague top of gravel.

- 44 Across from mouth of first creek upstream from Bennett Cr. gravel flat at 33 feet covered with fine talus material (addn) - fine talus, silt, 12' bedrock short beneath gravel. Unmeasured rock spurs at about 100 ft. Low 10' $\pm$ floodplain.

- 45 200' east of bridge at Eggar - good gravel at 54' $\pm$ no bedrock seen. Ordinary well rounded gravel.

- 46 1 mile approx west of Eggar, just before crossing bridge 20' bedrock. Surface of which is water worn and possibly wind cut. I do not think it gl. The rock is light with granite stringers. Granite has completely weathered away while other still shows good surface. Show this to Bayou.

- 47 Good gravel banks (N.S.) at entrance to wide Lynx Valley. It is approx. 10-12' and in place undisturbed by bedrock.

Wide straight stretch of valley must be due to rock character. Good gravel benches throughout the valley. And

stream faceted rock spurs at
about 200± (est.) feet.

- 48 Eastern end of Symmer Ranch
has apparent terraces at 24 ft.
and 52 ft. (hand leveled). However,
they are not always at the
same elevation, but vary
slightly. There are large talus
cones from a wall spreading
out on the 50' terrace. These
are largest exposures of terraces.
It would be a good idea to
check terraces at upper end
of valley.

- 49 1 mile below Rustic creek talus
cones on gravel. Terraces have been
become obliterated by deposition and
talus so that only local level
shows to advantage at 7'±. In
cut (125) by road hand leveled
exposed 15-20 ft bedrock and
24' gravel. Surface covered by
talus.

Check elevation on gravel
capped spurs just east of Sym-
mer Ranch lower. They seem
to be about 90'.

Measure spurs across river from
Rustic and upstream.

where river cuts into road W 1/2 Sec
35 there is thin skin of gravel on
20' (h.l.) bedrock.

Seems to me location of Rustic Ranch
has been shifted.

- 50 Douglass in section 36, good
coarse well rounded boulders
at 20 ft just above the river.
Low & flat plain on S. climbing
up on to divide. Found
whole mass of "lightening
material" - however, it may
well be quartz.

- 51 1/4 mile east Profile Rock on river.
bed at campground there is 24'
(h.l.) gravel bench. Coarse and
well rounded.

Aug 14th

House - 300 ft. upstream from
hill 33. There is 18' gravel
overlain by 4-6' silty talus
and a high 48' terrace (hill).
Looks as if 50' ago partially
through terrace.

Photo #10 - Daring Rd. View
east across Powder Valley
just upstream from mouth
Harrison. Possible erosion hill
visible on spur.

Aug 16 -

East from camp -

In valley of Spottedwood Cr. east bank
1 mi. N. Jack Spring Ranch, stream
cut in #3 shows -

18" black top soil with
some scattered feldspar.

18" light buff leached soil

↓ 8' exposed gravel well
stratified. Arkose
like feldspar, partially
caliche cemented.

Beds of coarse boulders
up to 15" diameter and
some coated with caliche.
Laguna (Pue) rocks with
a few sandstones.

One boulder pebbled.

1/2 mile east Jack Spring Ranch get #4
with good coarse gravel cap of bedrock
in the thickness. A great predominance
of ss. on lower slopes. Top has much P. & F.
Boulders are rounded and range in
size up to 30' (which is rare). Wind cut
spindles.

Cont. road. get higher #5 with similar P. & F.
gravel, wind cut. This on bedrock but thick-
ness unknown.

In vicinity of Krams the #4 is well preserved. Just east of station rd. cut with both coarse and fine Arkane-like gravel. Cross bedded and in spots cemented by caliche. Many ventifacts, some still in the gravel bank. One specimen shows possible striations.

Gravel pit between Krams & Hager. which shows gravel on Bule but thickness of gravel uncertain here. Not good bedding exposures.

Hill 6000 north Spring Meadows Ranch is of Bule with good gravel cap of igneous rock. But is as abundant as shown on old map. Thickness of gravel uncertain because of the slump.

Long ridge which runs SE, east of Decker & Price remains is gravel capped. It must belong to the #4 surface. Valley between it & RR is #3 and covered by wind blown sand. Cut hills show that beneath there is much pink feldspar.

Surface along RR shows typical coarse gravel all day, but in center is covered with wind blown sand.

West of Dover there is 4, 3, & 2, and good #5 beach around the Arkane pt.

Much gravel on Bule 1/2 mile E Dover on #4 surface. Caliche cemented.

Wild Horse Tit. - Much sand over the country. Bule (?) under wild horse which looks like Chamber Lake Tuff. Has lapillaries but could find no fossils. Medium size, well rounded, and decomposed gravel, about 20 ft on bedrock of tuff. Seems definitely to be #6 surface. Bule gravel

where it was S. P. between Dover & Hager about 4' fine pink gravel, or bedrock. Two about 1/2 mile W of Hager & bedrock is unconsolidated sand. Some coarse material in the gravel up to 8" diameter.

Coarse typical #4 gravel on hill 1/2 mile SE Hager - 5/34.

Driving east from Price 8 miles, 2 mi. south of Hager west to Hager & Ault saw no outcrops of gravel, but only flat, sandy country.

West from Ault to Ft. Collins, only gravel on high hills 5 miles W. of Ault. This gravel decomposed, much granite, much caliche and only about 2 ft exposed in rd. cut. This country is all covered with wind blown sand.

Old Ft-L is 2 mi N Ft. L -
 20 mi NN Torrington
 Strike N 70° E Dip 61° S. SE.

E Side uppermost lower Harrison occurs
 on the Laramie 3 miles S at level of
 400 ft. below top of Brule - which
 means a throw of 700 ft.

Minor faults - Sec 31 T. 26 N R. 15 W.
 major doming in Post Miocene with
 dips in Miocene to west of 1-3°.

Land

T 32 N R 69 W Sec 32
center E-W line

Sec 26

N of E South pt

T 32 N R 69 W Sec 29 + 30
N of E North 1/2

Flattop
of anticline

undecomposed
volcanic
pile

specimen
pit.

Sequence

1. Flattop penuplain

2. R. M. partial penuplain

3. Specimen Mtu volcanic pile = Basalt clay = Oligocene

4. uplift part Basalt - with perhaps basaltic in
plains

5. Antares

Miocene

6. Sherman penuplain

Pliocene? - Ogallala?

clatoplar

possible interpretation

columnar brown soil

Aug 22
 Photo 41 - Wind cut stone in situ
 1/2 mile W - Rockport, Colo.
 Fine sand
 with wind cut stone

A number of wind cut stones found in the deformed gravel - some of them are coated with caliche. Best are found near the upper surface.

Aug 24

Traverse up Spottedwood Creek

Good exposures of unconformity at base of Arkane. Much rounded Brule. One can make the definite observation that the Arkane is dipping to east more steeply than the present stream gradient.

With hand level near Halley's Ranch - High Plains 0° - Arkane 1°. Other measurements tend to show that the H.P. surface slopes about 1°.

On high surfaces beautiful specimens of round and pitted, grooved and polished stones. These are all large. Return Duck & Spottedwood Creek, 1 mi. W Halley's Ranch.

Another measurement H.P. to Arkane 4°

Head of Sand Creek Valley

Superb view
Arkane & Brule on east valley wall but not on west. Tilted red Fountain Tablelands, flat lying sediments. Seems to be a good deal of faulting. Alford cycle shows up well from here. There may be some Arkane on west side of valley. 4 or 5 erosion levels

can be seen. Grass on high ridge. Several good lower terrace levels seen in the Green and Valley.

Good ss. conglomerate as large chunk boulders on hill south of Green and Ranch.

At Lindemann's camp the pinkish color of the Brule is due to the very fine material from the overlying Arkane. The fine material is brownish. The feldspar pink. Brule is covered with feldspar from Arkane.

Aug 25th

Side pit on Laramie - with fine view
A #435 have again on Cretaceous River.
Low Tree Creek - east of Dorr has
flood plain, #2 + #3 surfaces below
the #4 at Dorr.
#3 has 2-10' gravel = 3' mixed brown
material on Cat. level 12' ± above
stream.

At NE corner of section being worked, the
#4 interfingers with sloped down to
#3 which is narrow, #2 quite
well developed on this side. The
#3 broad - well developed to east.
#1 very narrow and insignificant.

Particularly curious where it runs
west from Dorr crosses creek is the
only place where the #2 is really
developed, or can this be where
it is being cut out.

Aug 27th

Traverse down the North Fork.

At Livermore Road one can see
several terrace levels on the N.
Fork (5 rock cut apparently).
A good surface 200+ feet above
the river, with 4 above it. This appears
to fit in with the good surface
sloping outward from Livermore
Mt to the west.

At the North end the 2 hills covered
by River are gravel capped bed
rock which has been cut into by a
canyon of small stream flowing
from NE. Granite canyon.

Photo #3 View down North Fork
from just about opposite hill 6605.
This is terrace of 100+ feet above
the stream.

1/4 mile downstream there is good 8' fill
terrace.

In Sec 16 there is deep canyon cut into
the Prec bed rock. Stream may be
flowing not far from bedrock. About
canyon 500 ft. There is good 12' level
which is composed of sand, well rounded
and some sub angular blocks.

H.L. to top of remnant in Sec 16 and
found 180'. Behind remnant are
good accretion spurs. No good gravel

on these spurs. Weather now did residual material. Downstream $\frac{1}{4}$ - $\frac{1}{2}$ mile on W side are the same series of spurs. There is another level of spurs about 150' 200 ft higher and another 100' still higher.

NOTE The 3 terraces previously shown no gravel, just fine red wash.

Within $\frac{1}{2}$ mile upstream there are also several surfaces which with backshot h. l. to approx. 60'.

There seem to be 6 surfaces above the flood plain

Continuing down river, at 5 bank long sec. 16 there are several large and dissected alluvial fans. There is also a low gravel bench at

12' bench of gravel Sec 21 just upstream from horse. West side with high bench 150-200' behind. On east alluvial cones which belong to this 12' level & have been dissected.

At mouth of small gulch coming in from west (drawn in) there is on east side - flood plain 20', 60' & 168' H.L. terrace. The 168' has been reduced and should be about 200'. There is on W side a 250' surface (unmeasured) and a higher one at about 500'.

Almost at 5 boundary of Sec 21 there is good terrace level at 31 feet. Alluvial cone which come out on this dissected surface are being cut into. River flows 6' below with narrow flood plain. There is a flat on the alluvium at 12'. The 30' is the only good gravel remnant seen thus far.

Continuation of 20' gravel into Sec 28. 12' terrace has become coarse boulders. High terrace, unmeasured, 60' level, with still higher 200 ± level.

1/4 mile down stream.
Continuation of 30' + 60'
with good 150' H₂O on both sides
highest surface 250' ±.

The 150' is very prominent - takes in the
broad flat at head of river down-
stream. No gravel, it is a rock bench.
There are innumerable benches here,
but they seem to fall into 150', 250',
400' + Summit of 1000 ft ±, with
perhaps a lower 700' ± surface.

At head we find very large
boulders 8' + diameter which
are no longer moved by the
stream, also a 12' red dirt
30' level and a sandy
sheet in the river, with
bedrock benches at head of
stream.

At south end of head there
are excellent 12 to 15 +
30' terraces of quartz, in
part underlain by bed
rock. Gravel is medium
coarse and fairly well
rounded.

At N. E. head H₂O 12' + 35'
terrace. 35' of good gravel +

well developed

just beyond head there is good
150' unmeasured terrace - 1/4
mile upstream from head.
There are good rock spurs
across and with 150' both
upstream + down for 1/4 mile.

Head on W. Fork 1/4 mile E of
Ft Collins W. W. get good
flood plain, 12, 30' terraces.
Also higher rock at about
60' and 200' + rock bench.

Just above Ft. Collins W. W.
a 12 + 30' terrace, unmeasured.

August 28th

Green Ridge Traverse -

Start East Lake - recent gray drift and gently rolling topography. The whole surface is drift covered.

Between Laramie & Twin Lakes much drift with a few rocks mountainous surface on bedrock. Hummocky topography. Much light colored sandy drift.

First of Twin Lakes (these are slight water lakes). Much low swamp around them.

On north side looks like a small moraine. Bedrock hills showing up are all rock mountains. Note there is still a small patch of snow on the mts. - north side Laramie Peak.

Photo #4 - View south across Twin Lakes showing mts capped by dipping Tert. volcanics. Dip read from line with Brewster (not to strike) 7° dipping to NE.

At north end of Big Twin Lake there is outcrop of Gtff. No fossils. Specimens taken.

Continuing on trail to Laramie Poudre Tunnel, the ground is covered with residual boulders and spots of sandy drift. One pebble of gabbro was seen on hill south of the Tunnel. This must have been glacial. Rock outcrops have a rock mountain form with the steep side facing to the north.

Top of Green Ridge - Photo #5

Open forest of great relative flatness. Most of the rocks are of the same fine grained granite texture, and highly weathered. Surface covered with fine angular debris or fine scattered boulders of schists, which are relatively unweathered. If this surface was glacial it was long ago so that the material is chiefly altered. Several small pieces of gabbro found near edge of the Green Ridge surface.

Looking over valley of the Laramie above the tunnel - Photo #6 - cirque to west which in my opinion shows 3 stages of gl. high broad saddle above present cirque, which is a double cirque. The U shaped valley has been dissected.

Photo 7 - no moraines visible looking down the Laramie Valley, except a lateral at Middle Mt. and the Home stage at N. Wind. Mt. The valley floor is level & open because of the great amount of fill.

There is at the West Portal a small moraine and a lateral moraine stretching down the valley. This means that the floor to the east of the lateral is probably antedated from the former creek stage. This is about 8600.

Aug 29 -

Detailed traverse up S. L. P. from Gladstones

52 At Gladstones river has wide channel and good surface at 12' above the stream. Large alluvial fans spread out on this surface. Boulders are coarse and subangular. The smaller cobbles are the well rounded ones.

Same surface continues past Spencer Heights to

53 Camp Home (1/4 mile below P-S Tunnel) same 12' level continues on both sides of river. There is also a remnant of 30' bench H₂O of angular material. Behind it a very questionable 50' level. Maybe due to slump. Rather good lateral moraine at about 125'. It rests on bedrock on south side of valley. Numerous rocks. Mentioned surface on the north side. To the very top of valley wall there is evidence of all. Smoothing. Much weathering and talus. Most of boulders have lost their original surface through weathering.

54 At river bend at Tunnel the valley side has a profile. Whether or not these have any great significance is not known.

The 400' level seems to have a corresponding level on the north side. A large rock mountain at bend which is not shown on map but comes to the first notch at about 400'. It has terraces on it, and lateral moraine behind it and stretching out from it. There are possible box canyons behind this rock mountain.

- 55 At apex of bend in river there are 3 lower terraces on the south side. 1) River floodplain 1-5 feet 2) the 12 foot level (somewhat higher at the bend) and 3) a 30' terrace. These are all well defined. Ht. at 12, 27, and on north side one at 36'. This high one can be explained by the piling up of material behind the rock mountain, and I think it really fits in with the 30'. One can take no stock in the heights of the rock mountains for they may occur at any level. At L-P tunnel climbed on rock mountain. Some had gravel & of boulders caught in pockets, etc. so that they might be interpreted as terraces. However, the situation looks to me as if they were only remnants which represented significant stage.

except retreatal phase. They are not terrace levels. There is however a well developed terrace at 30' at mouth of tunnel (HL). The material of which it is composed looks almost like till, except that it shows stratification. Much fine material in this terrace.

Lateral moraine or landslide + pre-talus ridge. Later can be plausible. Photo last year with can in foreground. However, upstream it turns into the lateral moraine. River is running on bedrock. On both sides the boulders and gravel reach up to about 150 feet, but no terraces. Boulders rest on ice scoured surfaces.

- 56 500 upstream bedrock benches (?) at 15' above the stream in highest part. Much talus.
- 59 4 miles below BM 9220 there is approx 12' bedrock in stream with a 30' (unmeasured) terrace behind it. Large rock mountain and slump material which might be mistaken for a terrace. There is along here a series of bedrock spurs at about 54 feet. They are on both sides of river. The gravel on them and they do not seem to represent any stage which is directly related to the. They have been cut off by deglaciating.

As we turn bend, 1/4 mile below
river bridge the river flows
through a gorge of red rock,
which seems to be post-Holocene.
Within this there is a low gorge
12' deep, which may be post-
glacial. Looking back on
rock spurs one can see
that they are covered by boulders
dumped from the valley walls
but seemingly do not represent
a terrace. The rocks mentioned
are what hold up the lateral
moraines at the time of deposition.

58 Just 200 feet below bridge is a quartz-
stone 15' H.L. surface which may
be entirely glacial. It is
river as possible. One can see
by stream so that it flows 50 feet

Photo 8 — Post-Holocene canyon,
1/4 mile above bridge. This is
about 100 ± feet, to upper
surface and side walls show
old pit holes. Rocks above the
canyon form of surface. A small
box canyon within is partially
post-glacial. This is
due to river of being by the
Horn etc. Valley walls to top
show evidence of glaciation.

59 R. M. Freeland — 1/4 mile S.
BM 8220. 42' bench, just be-
fore the gorge previously described.
A portion of this bench has
fine well rounded pebbles with
interstratified tuff layers. This
is reworked material and was
the top of bench.

17 + 32' benches 200 feet above
the gorge, 1/2 mile south of bridge.
Good ledge, well rounded
gravel. The 17' bench may be
somewhat doubtful because of
road construction. This on the
side of rd. Above this gravel & dirt
caught behind the rocks mentioned
upstream.

60 1/8 mile downstream from stream junction
is good terrace on both sides of the
river at 16'.

61 Big South Junction — a 42' H.L. terrace
with about 32 feet below. In position
of last year. On right bank great
terrace looks cut into.
1/4 mile upstream there is drift on both
sides of the valley which I interpret
as lateral moraines. No terraces here.
There is some slight hint of sorting of
fine material.

Small 8' (unmeasured) terrace
just above the drift of the lateral
moraines.

b2 12' + 34' Hk. just north of BM 8665
Picture taken here last year showing
the old channels on the
terrace surface. This is immediately
below what appears to be the
first terminal moraine. This
where rd. used to cross river.
Photo taken here earlier in
season showing how rock debris
terrace and graded on bedrock.

Working backward from Garrison
River Bridge to old bridge.

L.R. bridge at well defined
terminal moraine. BM 8923

On 55 - a terrace at about 18' ±
unmeasured. The terrace from the
moraine forms good terrace at just
level - must measure - see p. 10
It would seem that both valley
walls are covered with fresh
drift into which the stream has
cut, leaving terraces.

Seem to be 2 (more recent)
moraines

Aug 30th

Trip to Iron Mt.

Start just below Cameron Pass.
The entire surface covered with
great much. The slump is com-
posed mostly of Tert. with some
fine large fragments of Pre E.

Specimen 1 - Trap rock from
lowest bedrock outcrop about
600' above creek. It deposited
in joints.

Flat on top of spur. All Tert. vol.
which has been highly weathered.
There are still a few fragments
of Pre E, but they are rare. On
iron mt. nothing is visible
but the Tert. although the Pre E
may be covered with talus.
However the spur to the south
looks as if it may be of Pre E age.
The flow on Iron Mt. look to
be fairly homogeneous in character
with some stalling out. With
a Brunton the Tert. slope to dip
approx 1° to the north.

At head of small creek at about
11,100 feet took specimen of rhyolite #2.
Also small thin section specimen. Note
the peculiar soft greasy mineral in the

rock. Could it be a quartzite or calcite? Remember that there is much calcite in the tuff. This rock has a peculiar pearly weathering surface and is full of tiny spines.

Photo #10 View north over the Ridge from point above small lake at Cameron Pass.

Photo #11 View south from same point showing rock of, in cirque of Northridge.

At this point there is no evidence of the Pre-E basement on which the Tert. rests. The Tert. of Iron Mt. seems to be dipping to the west - and what was beneath here was along the strike, approx. Specimen taken #3 of Tert. at top of spur.

Photo #12 View of Pre-E in contact with the Tert. The Pre-E is white coarse granite (Specimen #4). The outcrop is 200' high. Is it a fault or a contact of valley filling? The actual contact is deeply covered with talus. Some of the granite is coarse as to be pegmatitic. There is also some hornblende schist in this

granite.

Bottom of Joe Wright Creek about 10225' at top of pink rock which is probably Tert. Specimen #5. From the creek bed comes a calcite boulder #6. Where from? Probably river material.

Just over pass are highly decomposed white granite outcrops along road & creek. Below them on road an outcrop #7 of white Tert (?) volcanic with small jugs formed by solution (?) of flow.

Right on top of the Pass there is stream sorted gravel in creek & drainage ditch. This fluvial material is in the result of ponding of Joe Wright Cr. by glacial dam down and spill from across the divide.

At Joe Wright Ravine - along rd. outcrop of Tert., same as before. Lower bed, also fluvial sand. No real terraces above Joe W. Riv.

Aug. 31

Traverse up from Long Draw Rd. into Ford Cr. goes through Trap Cr. canyon which is cut into Pn E. At 3 miles near Trap Lake one cannot see Pn E under the Tert - probably because it is covered with talus. However, along rd. at Trap Lake there is Pn E and also Tert. tuff. Along the headwaters of Peterson Cr. + the leading into Ford Cr. there is Pn E on valley floor + wells with scattered outcrops of tuff and vol. breccias.

Photo #1 Terraces at junction Long Draw + C. la P. Lower surface 12' ± and higher one 20' ±

63 26' terrace across from shelter station at Hagens Cr. Lower terrace measured one at alt. 12' on opposite side.

64 1/2 mile above Hagens Cr. there is a post-glacial bedrock gorge 300 deep.

65 Upstream from gorge there is an unmeasured 25 ± terrace, extending for 1/2 mile.

At point where creek comes in from west there is the beginning of a lateral moraine, with a small patch which may well be a terminal

portion of the moraine complex. This the largest moraine complex seen in the area. It is very covered in most spots and has logs between moraine boulders. Behind it there seems to be a terrace of feet.

Photo #2 - looking downstream and showing moraine complex.

66 This large moraine complex continues to Chapin Creek. There is along this whole stretch of river a good 6-8' terrace or floodplain.

Traverse as far as turn in valley where we could see it from Trail Ridge Road. At this point the moraines die out. I don't think there was ever any Early Recent in this valley. This is Goffal Creek stage.

67 38' terrace just behind first hump of moraine material.

Tuff at Chambers Lake rises 23' - length of outcrop 570' approx.

23'
1500'

- 18 500' down from Jarama River.
 Bridge - terrace on S side 20'
 on N side 50' ±.
- 19 Ss across from 4th terrace, a
 30' + 66' (?) surface. The 66' may
 not be a valid terrace.

Sept 1, 1937

Wadsworth to Zimmerman's

- 10 8-12' terrace full broad
 meadow-like valley floor.
 Large talus cones spreading
 out on terrace.

1/4 mile west of Wadsworth's Ranch
 on N side at 32' HL.

Plane Table at Zimmermans (Barden)

- 1 HI = 2.9 Pr .7 BM made on
 rod 3.4 Dist 65 EI = 7660.
 approx.
- 2 110' 11 Pr EI 7652 approx.
 East end of Bridge across River
- 3 HI 3.1 Dist 260 Pr 0
 EI 7649
- 4 Dist 140' - 0' Pr. EI = 7652.
 This is east end of the baseline.
- 5 Dist { 830 5.1 L + 5° HI = 2.8
 { 820 C. EI 72 + 2.8 + 7652
 = 7726
- 6 0 + { 640' L + 7°30' + 82'
 { 625' EI =
- Top rock knoll with box canyon behind

✓ 7 0 1550' $\angle 10^{\circ} 45'$
 Head of small side gulch.
 1490' — +282' EI =

✓ 8 4' Rn 1220' $\angle 11^{\circ} 55'$
 High pt in front of highest box canyon

✓ 9 0 Rn 540' $\angle 2^{\circ} 45'$
 Break in terrace.

Setting up at Sta 5 — HI 3.1

✓ 10 0 Rn 680 $\angle +1^{\circ} 40'$
 High pt. on moraine S side

✓ 11 5 500' $\angle +5^{\circ} 5'$

✓ 12 0 170 $\angle +3^{\circ} 35'$

✓ 13 1.4 260 Nor.

Sta 14 Dist 560 Rn 4' HI = 3.4
 $\angle +2^{\circ} 30'$

Sept 2

Setting up at #14

	Rn	Dist	Cor Dist	$\angle -3^{\circ} 28'$
15	0	1800	Same	
16	0	800	792	$-4^{\circ} 45'$
17	12	660	Horizontal	
18	12	640	Same	-1°
19	12	1600	1550	$+10^{\circ} 15'$
20	12	240		$-3^{\circ} 15'$
21	3	110		$\angle +2^{\circ} 10'$

HI = 2.9

At Sta 20 HI = 3.2

22	8	440		$+2^{\circ} 10'$
23	8	70		-6° HI 2.9
24	12	240	233	$-15^{\circ} 10'$

From Sta 5

25	5	640'		$+10^{\circ} 45'$ HI 3.1
----	---	------	--	--------------------------

At Sta 25 HI = 3

26	0	660		$+5^{\circ} 40'$
27 (from 26)	8	540	(520)	$+11^{\circ} 45'$ HI 2.7

28	0	720	- 25'
Setting up again at 4 HI			
29	11	312	- 2'
30	0	600	+ 20'
31	0	940	+ 2° 35'
32	5	320	+ 2° 50'
33	7	450	+ 2° 52'
34	0	1500	+ 8° 30'
		1455 Cor.	
35	5	1400	+ 10'
		1355 Cor.	
36	4	1600	9° 20'
		1555 Cor.	

Elevations for points:

1-7660	9-7681
2-7652	10-7749 (E)
3-7649	11-7732
4-7652	12-7740 (E)
5-7726	13-7728
6-7737 (E)	14-7711
7-7937	15-7603 (?)
8-7897	16-7648

17-7702	40-7632 (E)
18-7691	41-7666
19-7980	42-7679
20-7688	43-7791
21-7688	44-7921
22-7682	45-8070
23-7694	46-7675
24-7624	47-7675
25-7744	48-7676
26-7823	49-7691
27-7719	50-7644
28-7711	51-7658-?
29-7633	52-off map
30-7659	53-7668
31-7697	54-7656
32-7666	55-7723
33-7669	56-7804
34-7874	57-7755
35-7893	58-7711
36-7910	59-7723
37-7661	60-7809
38-7640	
39-7665	

Sept 3

Sta 39 - HI = 3.2

39 8 520 $\angle = +1^{\circ} 23'$ (18.5)

38 4 460 $\angle - 2^{\circ} 30'$ (2)

39 8.8 380 Hor

40 12 860 $\angle - 80'$ (10.5)

41 8.3 800 Hor

42 8 780 $\angle + 1^{\circ} 40'$ (23)

43 0 840 $\angle + 8^{\circ} 55'$ (1.7)

44 4 1160 $\angle + 13^{\circ} 25'$ (2.1)

45 0 1400 $\angle + 17^{\circ} 45'$ (2.6)

46 4 520 $\angle - 55'$ HI = 3.2

49 3 580 Hor

48 4.2 240 Hor HI 3.2

49 2 140 $\angle + 5^{\circ} 50'$ (1.4)

50 12 600 $\angle - 2^{\circ} 15'$ (1.2)

51 12 700 $\angle - 45'$ (1)

52 12 2000 $\angle + 1^{\circ} 15'$ This is off map

53 0 720 $\angle + 25'$ HI 3

54 9.3 Hor

55 0 1440 $\angle + 2^{\circ} 5'$ (5.2)

56 0 1880 $\angle + 6^{\circ} 15'$ (1.2)

57 0 1580 $\angle + 3^{\circ} 5'$ (1.7)

58 4 1440 $\angle + 1^{\circ} 45'$ (1.7)

59 0 1500 $\angle + 2^{\circ}$ (1.2)

60 2 2000 $\angle + 4^{\circ}$ (1.4)

Sta 61 P. 53 HI =

12 600 Hor

62 2 340 $\angle + 15'$ (1.5)

63 7.2 960 $\angle + 35'$ (1.0)

64 12 340 $\angle + 1^{\circ} 30'$ (1.1)

65 12 800 $\angle - 3^{\circ}$ (1.1)

66 12 820 $\angle - 1^{\circ} 10'$ (1.0)

67 12 620 $\angle - 20'$ (1.3)

68 7 820 Hor

69 12 600 $\angle - 15'$ (1.6)

Sept 4			
Firm 68 145-3			
70	0	1780	$\angle + 1^{\circ} 10'$
71	3.5	1700	$\angle + 25'$
72	4	1600	$\angle + 1^{\circ} 45'$
73	2.5	1900	$\angle + 8^{\circ} 35'$
74	0	4000	$\angle + 12^{\circ} 5'$
75	12	720	$\angle + 1^{\circ} 11'$
76	7.8	280	14m
77	0	700	$\angle + 25'$
78	0	700	$\angle + 20'$
79	0	380	$\angle - 3^{\circ} 30'$

Firm 28

80	2	320	$\angle + 45'$
81	0	1440	$\angle + 6^{\circ} 20'$
82	4	640	$\angle + 14^{\circ} 58'$

83	12	220	$\angle + 1^{\circ} 5'$
Sta 83	HI 302		
84	12	160	$\angle - 11^{\circ} 15'$
85	4	290	$\angle + 7^{\circ} 10'$
86	12	120	$\angle - 17^{\circ} 30'$

There is on edge of bench 15' away river.

20 75
12 45
7 30

61 - 7677
 62 - 7680
 63 - 7683
 64 - 7683
 65 - 7626 (?)
 66 - 7651
 67 - 7665
 68 - 7673
 69 - 7665
 70 - 7712
 71 - 7684
 72 - 7721
 73 - 7953
 74 - 8496
 75 - 7667
 76 - 7662
 77 - 7675
 78 - 7674
 79 - 7647
 80 - 7706
 81 - 7867
 82 - 7710
 83 - 7705

84 - 7666
 85 - 7631
 86 - 7528 (?)

8496
 7647

 859

7953
 7647

 306

Sept. 6th - Last Day
 Picking up on flat.

✓ At mouth of Canyon - high gravel
 on bedrock. Scattered pebbles
 72 ft. this year. The gravel in cut
 is highly decomposed. That on
 the surface is not so highly
 decomposed.

① SW 1/4 Sec 10 - E side river a
 terrace at 24 feet. This about mid-
 way between 52 + 5200'. This appears
 to be possibly reduced. It may have
 been about 30'.

② When river enters the Sec 9 from N. it
 there is an 30' foot terrace of good
 coarse sand, mostly fine. East
 side of road. This is the terr. sand.
 Low 8' terrace at river.

③ 500 up stream on west side a
 8-12' gravel terr. covered by talus.

④ Sec 9, east side just before reaching
 bend gravel outcrops up to 26 feet
 typical fine gravel, etc. well
 rounded.

5 At Poudre Canyon, no gravel found
 on the bedrock 74' above river. This
 lower ridge suggested by Boyer for
 investigation.

24% In bend just beyond Canyon canyon.

the lower terrace at 24 feet - below
 the measured 36' terrace.

Straight stretch below Ft. Collins
 W.W. 10' gravel bench on east side.
 1/2 way on the left side is good gravel
 a and gravel at 22 feet. Because of
 dirt on right hand to get actual
 measurement.

1000' above Ft. Collins down there is a
 15' ± gravel terrace. It may be some-
 what reduced. On road side of river
 there is a 20' H.L. terrace, covered by
 fine talus.

Continuation of this terrace around
 bend where river turns to the south.

Along N-S stretch on 12 foot gravel on
 the east side. At bend on W side the
 same terrace, measured just beyond the
 rock above another outcrop of gravel up to
 20 feet and covered by talus.

When river bends to north to go around sharp
 point on north of bend there is a 20' ± un-
 measured terrace of typical gravel.

At apex of this bend there are two terrace
 levels of 13 and 30 feet (highest was
 previously hand leveled).

Around the bend there is a low terr. on
 N side, unmeasured at 2'.

Through this particular stretch at Big

⑥

1/2
2/3

⑦

15
0
20
0

⑧

18
0
20
0
20
11

⑨

20
0
12
0
3
0

⑩

2
0

Today there are relatively few
remnants.

- ⑪ In Sect - straight strike at 6 in -
uncovered bedrock in which
unconformity with a 12' bench
of gravel. This on north side.
just before bend at 1/2 mile from there
is gravel up to 40' high which is
about 10 ft. or bedrock the rest of
the way to river.

- ⑫ Part of which I climbed today
covered slope. Some river there is
a 12' x 30' and a 50' (quite irregular)
which are estimated and not h.l.
There is about 100' = 200' of 5 feet
along from this point up stream.
Gravel!

- ⑬ Just east of Rainbow Ridge there is the
unconformity. At Rainbow
Ridge and elsewhere is the East
Hewlett measurements.

- ⑭ At Hewlett Creek there is a thin
layer of 1/2 inch down river on
the south side up on valley
is gravel but takes slope of hill
seems to be accidental.

At Hewlett Creek there is on the south
side a gravel terrace of coarse boulders
at 42' above the river. This may be still
even higher, but the relations are not
clear.

Above Hewlett Gulch 6-8 Terrace
at bend Sec 3. At 18' gravel to
covered by talus. (15)

32 feet gravel terrace covered by fine
talus and above on hillside
gravel at 42 feet. This was point
1/2 mile east of Watsons Gulch. At
bend on road just 50 feet west of
32 + 42 there is 18' foot gravel
terrace. 100' ± 50 feet. (16)

The 18 + 42' surface coming up to Watsons
Gulch. (17)

A few 6-8 foot terraces up to 200' on
Thompson's. There there is an apparent 50'
or ± unmeasured on the side along from
the north. Very coarse boulders which
are not of this material. (18)

About 1/2 mile west of Watson Gulch are
a series of terraces on the east side
at about 450 feet - unmeasured.
Blas at 150 - 200'. (19)

Sept. 7 -

Rechecked upstream from Thompson's 5900'. Start of the Little Narrows.

There seem to be numerous rock spurs which average about 20' above the level of the water. Range from about 12 to 30 feet. Upper surface seems to be water worn.

Just beyond Tunnel there is an old 30' wide abandoned bench. This is examined. There are several of these benches at about ascending heights. This is NW 1/4 Sec 5.

Photo #1 View at upper end of the Little Narrows showing back of terrace and the bedrock spurs.

At bend SW 1/4 Sec 5 noted higher bedrock with an old terrace on top which has been dissected. Photo #2 of this, spoiled so #3. The bedrock (14' high) is about 96' high. must be about 50' in the past at 6050 feet.

There is also low 8-12' gravel bench which carries up the upper 1/2 mile to the Prairie Landing.

At Stevens Gulch good gravel on bedrock at various levels. Just 1000' west of Gulch bedrock spurs at about 60', and farther on (500') bedrock spurs at about 20', unmeasured. Then about 700' below bridge over S. R. R.

Sharp Mt. Narrows -
Bedrock spurs at many elevations.
Between bridge & bend at 40' & 150' (unmeasured).
" bend & upper bend at 15' & 40' (unmeasured).

Photo #4 - shows profile up to 40' ± above river in S. part of bend. These benches seem to continue through out these narrows (Big Narrows).

at bend just before being narrows there is a (previously measured to) bedrock bench at 20 feet with 20 feet of gravel on it and above it a spur which must be at about 100+ feet at the narrow bend. The level of the river has been raised in these narrows due to the filling of the stream at that a road could be put through that place the drowned trail.

At camp at end of narrows before Elkton Cr. there is 15' bedrock and a 30' gravel terrace on both sides of river. There is a 15' terrace on the bedrock. 500' upstream the 15' rises to 20' away from the stream and seems almost to merge with the 30' terrace level. Toward

the river the bedrock is stripped bare and shows a well weathered surface, so disintegrated that not much of the effects of water wear remain.

- (28) Below main Elkhorn G. there are numerous terraces at about 150' and on west side a good one 6-8' high.

(29) At Elkhorn G. bend a 13' gravel terr. underlain by bedrock which in some spots reaches the surface and a 42' terrace (edge) with a border of fine Tert. soil from the north flattened at top. This indicates a correlation with some working, but is far from conclusive.

700 ft below Little South a 30' surface on west side. If it was not for the river etc. it is the same as the 42' - 50' surface.

- (30) Upstream from Little South for about 1/2 mile a 6-8' surface (main) and 3/8 mile above good 2' on 33 at about 100' (main) 2' rock spur.

- (31) At Ft. Collins park there is a 5' - 32' terrace level well shown. The higher surface is underlain by bedrock which in some places upstream 1000' the 5' is plain out and is replaced by a 12' surface

of granite. Coming from park there is a surface higher than the 32' level possibly correlated with it since it is farther from the river. (32)

On 55 700' below river bridge at Elkhorn there is good 15' gravel terr. which extends for some distance. (33)

1/2 mile upstream from Elkhorn 18' on 43 and 50' on 35 (main). This was the polished rocks. Bedrock under some patches of Tert. This is 1/4 mile east of bridge. (34)

Rock spurs of Symon Valley east and one about H.L. above the 50' (60 at rd.) terrace of 216 ft H.L. (35)

Phot #6 showing the 50' terrace with alluvial fan on it and the bedrock spurs on the north valley wall. These spurs show up nicely here and are made of less bedrock a replacement of old valley stage.

Half way between bridge and western valley measurement is a 31' terr. The surface of bedrock up to 12-15' in some places. It is a good 12' H.L. about equal in elev. to the 52' demonstration. (36)

300' west of bridge (which is near Dadd's) there are good terraces at H.L. 12, 36 & 108'. The 108' is unique with well rounded Tert. & quartz decomposed granite. It is older than the gl. It is (37)

on bedrock and covered by
talus. Study.

38 1/2 mile up valley at Sudden Meadows
get 3-12 (furns) with about a 40'
above. 500' upstream get about
20' (furns) terrace.

1 mile up valley there is a 12' & 42'
Ht. ter. but additional cover has been
the ter. surfaces. On 3/5 of valley is a
approx. 6 ter. which is not a true ter.
ter. may be just a part of a talus cone
and into that place, the Ht. is not a true
ter. a definite ter. talus.

40 700 ft. further is the cut and ter. Pres-
umably measured. Found that
at the Sudden Ranch house is a Ht.
36' on Ns and a 12' (furns) on the
Ss.

1/2 mile below Ruster the approx
same level as the 36 appears on
the Ss of the valley, about an
approx 12' level.

41 1/2 mile up at 9220 on Ss of river
there is 8' terrace then an at
96' - being banded up from
the Ns and that across. Can
this connect up with that below
at 108? This one is of bedrock
and does not seem to carry the
typical gravel, as seen by the
field of fossils.

Rough Ranch - just below a 15' ± on
Ss, have the Ws line 6' forming
the dipplain, with abundant corals
on it. 42

the Ss 36 measurements are at upper
end of Sudden Valley. On the South
side there seems to be a 30' ± terrace
but couldn't get over so am not sure. 43

1/2 mile E Profile Rock (just in the black
where)
2 gravel terraces - coarse at Ht.
at 80 & 18'. There is here a 1-2 rock from which
on first glance looks like a lateral moraine.
Under Profile Rock on Ss on 8' ter. 44

On Ss 1/2 mile west of Sudden a 12'
(furns) ter. On Ns a Ht 30' foot ter.
which is a mixture of angular
and well rounded boulders. 45

At town on road just beyond Sudden on the
map there is a Ht 36 foot ter. on
N. S. The gravel is both large & medium, but
extremely well rounded. Below it is an 8 Ht.
foot level. 46

Gravel bed mts are 8-10' terraces and
a 30' level (furns). 47

Just above head of river moraine of lower
level is on Ss a 110-12 and 35' level Ht.

= Just east of Sudden Ranch house there is
100' Ht. gravel on bedrock. Is not this the
main? It is coarse & medium and of

many varieties but I could find
no Tert. volcanics. It fits in with
the general at Indian Meadows.

Symant Valley - east end has
18 + 36' hand leveled ter. Between
the 24 + 52 + one more. Today
there is a 24' level. These all
seem to be in one
another over the 2 miles
approx. and are indistinguish-
able. They are also partially
covered by talus and this
can't be separated without
detailed mapping. There
seems to have been some
washing of the top. Plotting
may bring out the relation-
ships.

Sept. 8

H-28 foot ter. which is covered by
fine talus. This is level east of Pond
bottom and around corner, 1000 ft
from top of gulch & just west of highest
H-28 spur.

Trip to Prairie Divide for photos,
etc.

Sept 9th

Julesburg -
Hwy to Holyoke + Wray -

S. Platte an anastomosing
stream. Typical pink granite
fragments in many stream beds.
River is subject to occasional
major floods up to RR tracks.
River 6-8' below a wide sand
covered flood plain terrace.

Above this is a grit which seems
to be caliche cemented (Suggs
has found bones below it which
have been identified by Tappin
man as Pleistocene. I doubt it.)

Above on hill slopes is what may
be Bule, pinkish at top and
hills covered with gravel - one
found of Tert. vol. Mamm. size of dog.

Above this are unconformable and
highly crossbedded grit of coarse
material which is stained black
this may be Bule or a Ogallala
paleo forest in it which may be
Bule.

The highest hills are gravel capped (8' dia
max) which is crossbedded and fine
and which has a good deal of caliche in

layers. This material is mainly
schists in the form of gravel. The
finer material is the light colored.
Wind blown sand on top.

Julesburg - and rd. south of river
2 mi. west Julesburg another
surface between floodplain +
the first rock upland bench.

Sherman	Black Plains	1000-1200
Leslie	Wildhorse	600-800
Hecla	Coalbank	250-300
	Timnath	150
	to of	Home 90
	Kinsley	C. Co. 50
	Kennett	Q. D. 30
	?	Post 20
	?	Beck 10

For Bryan to see -

1) Gravelly boulders on fine material
just east of Prairie landing

Sept 6

Breakfast 1.02

6 gas 1.20

lunch 1.75

Mr. Kuitzer
U. S. Forest Service
Ft. Collins, Colo.

Information on wells.

Recent physiographic develop-
ment along the northern
Front Range -
P. B. - Grand Pinnacle
4443 + 43000 100 ft
uniting 1937, Denver Colo.

DISTANCES FROM CENTER OF ROADWAY FOR CROSS-SECTIONING.

ROADWAY 14 FEET WIDE. SIDE SLOPES $1\frac{1}{2}$ TO 1.

FOR SINGLE TRACK EMBANKMENT.

	0	.1	.2	.3	.4	.5	.6	.7	.8	.9	
0	7.0	7.2	7.3	7.5	7.6	7.8	7.9	8.1	8.2	8.4	0
1	8.5	8.7	8.8	9.0	9.1	9.3	9.4	9.6	9.7	9.9	1
2	10.0	10.2	10.3	10.5	10.6	10.8	10.9	11.1	11.2	11.4	2
3	11.5	11.7	11.8	12.0	12.1	12.3	12.4	12.6	12.7	12.9	3
4	13.0	13.2	13.3	13.5	13.6	13.8	13.9	14.1	14.2	14.4	4
5	14.5	14.7	14.8	15.0	15.1	15.3	15.4	15.6	15.7	15.9	5
6	16.0	16.2	16.3	16.5	16.6	16.8	16.9	17.1	17.2	17.4	6
7	17.5	17.7	17.8	18.0	18.1	18.3	18.4	18.6	18.7	18.9	7
8	19.0	19.2	19.3	19.5	19.6	19.8	19.9	20.1	20.2	20.4	8
9	20.5	20.7	20.8	21.0	21.1	21.3	21.4	21.6	21.7	21.9	9
10	22.0	22.2	22.3	22.5	22.6	22.8	22.9	23.1	23.2	23.4	10
11	23.5	23.7	23.8	24.0	24.1	24.3	24.4	24.6	24.7	24.9	11
12	25.0	25.2	25.3	25.5	25.6	25.8	25.9	26.1	26.2	26.4	12
13	26.5	26.7	26.8	27.0	27.1	27.3	27.4	27.6	27.7	27.9	13
14	28.0	28.2	28.3	28.5	28.6	28.8	28.9	29.1	29.2	29.4	14
15	29.5	29.7	29.8	30.0	30.1	30.3	30.4	30.6	30.7	30.9	15
16	31.0	31.2	31.3	31.5	31.6	31.8	31.9	32.1	32.2	32.4	16
17	32.5	32.7	32.8	33.0	33.1	33.3	33.4	33.6	33.7	33.9	17
18	34.0	34.2	34.3	34.5	34.6	34.8	34.9	35.1	35.2	35.4	18
19	35.5	35.7	35.8	36.0	36.1	36.3	36.4	36.6	36.7	36.9	19
20	37.0	37.2	37.3	37.5	37.6	37.8	37.9	38.1	38.2	38.4	20
21	38.5	38.7	38.8	39.0	39.1	39.3	39.4	39.6	39.7	39.9	21
22	40.0	40.2	40.3	40.5	40.6	40.8	40.9	41.1	41.2	41.4	22
23	41.5	41.7	41.8	42.0	42.1	42.3	42.4	42.6	42.7	42.9	23
24	43.0	43.2	43.3	43.5	43.6	43.8	43.9	44.1	44.2	44.4	24
25	44.5	44.7	44.8	45.0	45.1	45.3	45.4	45.6	45.7	45.9	25
26	46.0	46.2	46.3	46.5	46.6	46.8	46.9	47.1	47.2	47.4	26
27	47.5	47.7	47.8	48.0	48.1	48.3	48.4	48.6	48.7	48.9	27
28	49.0	49.2	49.3	49.5	49.6	49.8	49.9	50.1	50.2	50.4	28
29	50.5	50.7	50.8	51.0	51.1	51.3	51.4	51.6	51.7	51.9	29
30	52.0	52.2	52.3	52.5	52.6	52.8	52.9	53.1	53.2	53.4	30
31	53.5	53.7	53.8	54.0	54.1	54.3	54.4	54.6	54.7	54.9	31
32	55.0	55.2	55.3	55.5	55.6	55.8	55.9	56.1	56.2	56.4	32
33	56.5	56.7	56.8	57.0	57.1	57.3	57.4	57.6	57.7	57.9	33
34	58.0	58.2	58.3	58.5	58.6	58.8	58.9	59.1	59.2	59.4	34
35	59.5	59.7	59.8	60.0	60.1	60.3	60.4	60.6	60.7	60.9	35
36	61.0	61.2	61.3	61.5	61.6	61.8	61.9	62.1	62.2	62.4	36

Calculated by Julien A. Hall, M. Am. Soc. C. E.

MADE IN GERMANY.

R.