

tained from the Duck Disease Research Laboratory (Eastport, N. Y.) and the Division of Laboratories and Research, N. Y. State Health Department.

Most of the *C. melanura* breeding sites were found in the Peconic River drainage system and near the cool, spring-fed streams flowing into the bays along the south shore. It was interesting to note that the breeding sites in densely populated areas of Nassau and Suffolk counties were restricted to undisturbed parks and large estates. No breeding was found along the north shore of

Long Island, which has few undisturbed cold streams or bogs due, in part, to the dense population in the western part and extensive potato farms in the eastern part.

Reference Cited

COLLINS, D. L. 1960. Status of eastern equine encephalitis and the mosquito vector potential in New York State. *N. Y. State Jour. Med.* 60:1225-1229.

OPERATIONAL NOTES

IMPROVED URBAN ADULT CONTROL OPERATIONS WITH AN ELECTRIC CLUTCH

G. A. THOMPSON

Director, Jefferson County (Texas) M.C.D.

In 1958 the Jefferson County (Texas) Mosquito Control District redesigned their eight Buffalo Turbines so that they could be operated by one man, rather than the two men previously used. There were numerous technical difficulties that needed solving. One of the more annoying was the deposition of dust in the turbine funnel and on the ground while the operator was loading the hopper. Unless the engine was stopped while loading, enough dust fed into the blower to deposit sufficient dust on the ground to burn grass and other vegetation. This resulted in a few complaints.

The regular mechanical clutch was provided with a control so that it could be operated from the driver's seat. The early attempts used an iron rod from the clutch arm, through the back of the cab of the truck and into the cab next to the driver. Although the design worked, it was very noisy and necessitated constant maintenance to keep the clutch adjusted. A second design involved the use of flexible cables, such as are used on boats to control the engine from a position at the wheel. These cables are capable of transmitting up to a thirty-pound thrust. The flexible cables were an improvement but were not the answer to the problem.

A search for a device to disengage the engine from the turbine and agitator led to the installation of an electric clutch. It is recommended that a "coupling-clutch" be used. A simple clutch requires a much greater degree of shaft alignment than is necessary with the coupling-clutch. The latter costs but little more, and installation is rather simple. In the normal construction of a Buffalo turbine, the drive pulley for the agitator is located on the engine side of the coupling to the turbine. This drive pulley

should be relocated on the turbine side of the new coupling-clutch, completely disengaging the engine from the dusting mechanism. In the event that the modification is made to the small Buffalo that is simply a duster, the old mechanical clutch can be inactivated and remain in place as a pulley. We have had no experience with the electric clutch on the sprayer-duster models.

The ratings as published by the electric clutch manufacturer show that a 6" clutch should transmit the torque of an 8.25 horsepower engine, the normal power supply for the small turbine. However, to be on the safe side, we installed the 8" clutch. We do not recommend the smaller clutch as there is considerable slippage when the 8" clutch is engaged. We were unable to secure satisfactory performance with the one six-volt clutch we bought for installation on an old truck. A twelve-volt system seems to provide ample magnetic force to keep the clutch engaged. Once the clutch is adjusted properly there is little maintenance to the mechanical parts. However, the slightest weakness in any of the electrical connections will result in malfunction of the clutch. The electricity is carried to the electromagnet through a paired, double brush arrangement on commutator rings, very similar to the collector rings of an alternator. The positioning of the brush hanger is critical. Too little pressure results in poor contact and too much contact results in excessive brush wear. The brush assembly must be shielded as much as possible from dust to prevent excessive wear of the brushes and collector rings. Dust can also pack in the brush hanger and inactivate the brushes. We have found it advisable to maintain a good supply of brushes and brush hangers to avoid lengthy shut-downs.

We have found the electric clutch an efficient tool, improving public relations in our dusting program in urban areas. The complete shut-down of the dusting apparatus provides for dust-free cross streets, parked cars and areas inhabited by persons allergic to B.H.C. dust.